



Portland General Electric Company
 Trojan Nuclear Plant
 71760 Columbia River Hwy
 Rainier, Oregon 97048
 (503) 556-3713

May 30, 1991
 WRR-116-91

U.S. Nuclear Regulatory Commission
 Document Control Desk
 Washington DC 20555

Gentlemen:

SPECIAL REPORT

Limiting Condition for Operation (LCO) 3.3.3.3.b, "Seismic Instrumentation", of the Trojan Technical Specifications (TTS) requires submittal of a Special Report if one or more seismic monitoring instruments are inoperable for more than 30 days. Portions of the seismic monitoring system were removed from service, beginning on April 20, 1991, to support Plant refueling maintenance activities and for the performance of Technical Specification required Channel Calibration on the seismic monitoring instrumentation. The required maintenance and calibrations are expected to be completed by June 7, 1991. The seismic monitoring instrumentation will be returned to operability when this work is completed.

Sincerely,

W. R. Robinson
 W. R. Robinson
 General Manager
 Trojan Nuclear Plant

c: Mr. John B. Martin
 Regional Administrator, Region V
 U.S. Nuclear Regulatory Commission

Mr. David Stewart-Smith
 State of Oregon
 Department of Energy

Mr. R. C. Barr
 USNRC Resident Inspector
 Trojan Nuclear Plant

9106050261 910503
 PDR ADCK 05000344
 S PDR

1/0
IE22