

July 10, 1972

U.S. Atomic Energy Commission
Directorate of Regulatory Operations
Region III
700 Roosevelt Road
Glen Ellyn, Illinois 60137

Attn: Boyce H. Grier
Regional Director

Dear Mr. Grier:

Further to my letter of June 29, 1972, I would like to submit the following answers to the items on non-compliance on license 22-13585-01 and 22-13585-02G cited in your letter of June 5, 1972.

License No. 22-13585-01

1. All byproduct material above the license limits of 36 millicuries of Promethium-147 will be returned to the manufacturer or other persons licensed to receive it.
2. All radioactive material has been removed from the premises of 1215 Second Avenue North, Minneapolis, Minnesota, so no survey is now needed.
3. All radioactive material has been removed from the premises of 1215 Second Avenue North, Minneapolis, Minnesota.

License No. 22-13585-02G

1. New labels will be procured which will have the model number on them and will show the correct quantity of radioactive material contained in each sight.

Corrected labels will be sent to the owners of the 10 hand guns which have incorrect labels. The owners will be told to replace the old labels with the new ones.


9106170273

JUL 17 1972

9106170273 910509
PDR FOIA
BAZZANE90-504 PDR

2. A correct copy of Appendix D, 10CRF20 will be sent to all general licenses in the future. The 10 general licenses who have received incorrect copies in the past will be sent correct copies as soon as they can be obtained. This error came about because we were sent the wrong material by the AEC when we originally asked for a copy of Appendix D, 10 CRF20.

Very truly yours,



E. F. Knutsen
Nite-Site, Inc.

EFK/caj