

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-186/83-02(DRMSP); 70-270/83-01(DRMSP)

Docket Nos. 50-186;  
50-270

Licenses No. R-103;  
SNM-247

Safeguards Group II

Licensee: University of Missouri  
Columbia, MO 65201

Facility Name: Research Reactor Facility

Inspection At: Columbia, MO

Inspection Conducted: July 13-15, 1983

Date of Last Material Control and Accounting Inspection: July 29-31, 1981

Type of Inspection: Unannounced Material Control and Accounting

Inspectors: J. R. Knudsen for  
T. J. Madedo  
Physical Protection Inspector

7/29/83  
Date

J. R. Knudsen for  
G. M. Christoffer  
Physical Protection Inspector

7/29/83  
Date

Approved By: J. R. Knudsen for  
J. R. Creed, Chief  
Safeguards Section

7/29/83  
Date

Inspection Summary

Inspection on July 13-15, 1983 (Reports No. 50-186/83-02(DRMSP);  
70-270/83-01(DRMSP))

Areas Inspected: Facility organization and operation; measurement and statistical control; shipping and receiving; storage and internal control; inventory; and records and reports. The inspection involved 25 inspector-hours onsite by two NRC inspectors.

Results: The licensee was found to be in compliance with NRC requirements in the six areas examined during the inspection.

(Details - PART 2.790(d) INFORMATION)

ATTACHMENT CONTAINS  
10 CFR 2.790(d) INFORMATION