

LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 2, 1983

W3I83-0257
Q-3-A35.07.80

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 80
"Unsatisfactory Stroking of EFW Pump
Turbine Steam Shut Off Valves"
Second Interim Report



REFERENCE: LP&L letter W3I83-0178 dated May 20, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC on July 29, 1983.

Rework of the valves in accordance with the manufacturer's recommendations has been completed and we are presently selecting an independent laboratory to test the valves under service conditions. Completion of this testing and evaluation is anticipated in December, 1983.

A Final Report will therefore be submitted to the USNRC by January 13, 1984.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/WAC/DEB:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8308120194 830802
PDR ADOCK 05000382
S PDR

IE-27

70