

POWER & LIGHT PO BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 29, 1983

W3183-0255 Q-3-A35.07.77

Mr. John T. Collins, Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 77

"Inadequate Containment Purge Valves

Closure Time and Flow Rate"

Fourth Interim Report

REFERENCE: LP&L letter W3183-0230 dated July 5, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than July 29, 1983.

The supporting documentation for this SCD is presently under review. Completion of this review is expected in September 1983.

A Final Report will therefore be submitted to the USNRC by October 14, 1983.

Very truly yours,

F. J. Drummond

Project Support Manager - Nuclear

FJD/WAC/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director Office of Management Information and Program Control U. S. Nuclear Regulatory Commission Washington, D. C. 20555 4) Mr. W. M. Stevenson

8308160212 830729 PDR ADOCK 05000382 S PDR

IE-27