

Docket File 40-8681
PDR/DCS
Region IV
PHildenbrand
WDEQ
URFO r/f

40-8681/PRH/84/10/22/4

- 1 -

OCT 25 1984

URFO:PRH
Docket No. 40-8681
04008681541E

MEMORANDUM FOR: Docket File No. 40-8681
FROM: Paul R. Hildenbrand, Project Manager
Licensing Branch 1
Uranium Recovery Field Office, Region IV
SUBJECT: ENERGY FUELS NUCLEAR, WHITE MESA MILL;
CHANGE OF RADIATION SAFETY OFFICER

By letter dated September 28, 1984, and in accordance with License Condition No. 11, Umetco Minerals Corporation, the new operator of the White Mesa Mill facility, submitted information relative to the experience and education of their proposed new Radiation Safety Officer, Mr. Scott Schierman.

URFO staff have reviewed Mr. Schierman's qualifications and have concluded that they meet the requirements of License Condition No. 11 of SUA-1358 and the guidelines of Regulatory Guide 8.31, "Information Relevant to Ensuring that Occupational Exposures at Uranium Mills Will Be As Low As Reasonably Achievable."

151

Paul R. Hildenbrand, Project Manager
Licensing Branch 1
Uranium Recovery Field Office
Region IV

Original Signed By
Edward F. Hawkins
Approved by: Edward F. Hawkins, Chief
Licensing Branch 1
Uranium Recovery Field Office, Region IV

Case Closed: 04008681541E

OFC	URFO	URFO					
NAME	PHildenbrand	EHawkins					
DATE	84/10/23	10/25/84					

9411020255 841025
PDR ADOCK 04008681
C PDR

9411020255



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

URANIUM RECOVERY FIELD OFFICE
BOX 25325
DENVER, COLORADO 80225

OCT 25 1984

URFO:PRH
Docket No. 40-8681
04008681541E


MEMORANDUM FOR: Docket File No. 40-8681


FROM: Paul R. Hildenbrand, Project Manager
Licensing Branch 1
Uranium Recovery Field Office, Region IV

SUBJECT: ENERGY FUELS NUCLEAR, WHITE MESA MILL:
CHANGE OF RADIATION SAFETY OFFICER

By letter dated September 28, 1984, and in accordance with License Condition No. 11, Umetco Minerals Corporation, the new operator of the White Mesa Mill facility, submitted information relative to the experience and education of their proposed new Radiation Safety Officer, Mr. Scott Schierman.

URFO staff have reviewed Mr. Schierman's qualifications and have concluded that they meet the requirements of License Condition No. 11 of SUA-1358 and the guidelines of Regulatory Guide 8.31, "Information Relevant to Ensuring that Occupational Exposures at Uranium Mills Will Be As Low As Reasonably Achievable."


Paul R. Hildenbrand, Project Manager
Licensing Branch 1
Uranium Recovery Field Office
Region IV

Approved by: 
Edward F. Hawkins, Chief
Licensing Branch 1
Uranium Recovery Field Office, Region IV

Case Closed: 04008681541E