



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGIC : 'V  
611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

FEB 13 1995

Wolf Creek Nuclear Operating Corporation  
ATTN: Neil S. Carns, President and  
Chief Executive Officer  
P.O. Box 411  
Burlington, Kansas 66839

SUBJECT: NRC INSPECTION REPORT 50-482/94-19 AND NOTICE OF VIOLATION

This refers to the inspection conducted by Mr. J. F. Ringwald and Ms. J. L. Dixon-Herrity of this office on December 18, 1994, through January 28, 1995. The inspection included a review of activities authorized for your Wolf Creek Generating Station facility. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements.

Based on the results of this inspection, certain licensed activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of concern because it suggested the absence of a questioning attitude on the part of security personnel, and the failure of the security program to require adequate periodic inspection requirements which would have identified this violation. No response to this violation is required because of your prompt, immediate corrective actions and your initiation of a PIR to evaluate the need for further actions to prevent recurrence.

We identified a violation of Technical Specification 6.8.1.a, in that locked valve administrative procedure requirements were not followed. This violation is not being cited because the criteria in paragraph VII.B.1 of Appendix C to 10 CFR Part 2 of the NRC's "Rules of Practice," were satisfied. This violation was of limited significance and corrective actions were appropriate.

One unresolved item was identified concerning your identification of an unlocked door which controlled access to a locked high radiation area. This matter is discussed in Section 6.2 of the enclosed inspection report.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room (PDR).

9502160067 950213  
PDR ADOCK 05000482  
G PDR


JEOL

Wolf Creek Nuclear Operating  
Corporation

-2-

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

*for*   
A. Bill Beach, Director  
Division of Reactor Projects

Docket: 50-482  
License: NPF-42

Enclosures:

1. Appendix A - Notice of Violation
2. Appendix B - NRC Inspection Report  
50-482/94-19

cc w/enclosures:

Wolf Creek Nuclear Operating Corp.  
ATTN: Vice President Plant Operations  
P.O. Box 411  
Burlington, Kansas 66839

Shaw, Pittman, Potts & Trowbridge  
ATTN: Jay Silberg, Esq.  
2300 N Street, NW  
Washington, D.C. 20037

U.S. Nuclear Regulatory Commission  
ATTN: Regional Administrator, Region III  
801 Warrenville Road  
Lisle, Illinois 60532-4351

Wolf Creek Nuclear Operating Corp.  
ATTN: Manager Regulatory Services  
P.O. Box 411  
Burlington, Kansas 66839

Missouri Public Service Commission  
ATTN: Assistant Manager  
Energy Department  
P.O. Box 360  
Jefferson City, Missouri 65102

Wolf Creek Nuclear Operating  
Corporation

-3-

Kansas Corporation Commission  
ATTN: Chief Engineer  
Utilities Division  
1500 SW Arrowhead Rd.  
Topeka, Kansas 66604-4027

Office of the Governor  
State of Kansas  
Topeka, Kansas 66612

Attorney General  
Judicial Center  
301 S.W. 10th  
2nd Floor  
Topeka, Kansas 66612-1597

County Clerk  
Coffey County Courthouse  
Burlington, Kansas 66839-1798

Kansas Department of Health  
and Environment  
Bureau of Air & Radiation  
ATTN: Public Health Physicist  
Division of Environment  
Forbes Field Building 283  
Topeka, Kansas 66620

FEB 13 1995

Wolf Creek Nuclear Operating Corporation

-4-

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan  
 Branch Chief (DRP/B)  
 Section Chief (RIII, DRP/3C)  
 SRI (Callaway, RIII)  
 Project Engineer (DRP/B)  
 Branch Chief (DRP/TSS)  
 A. B. Beach (D/DRP)

Resident Inspector (3)  
 DRSS-FIPB  
 RIV File  
 MIS System  
 Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME:r:\\_wc\wc419rp.jfr

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SRI:DRP/B	RI:DRP/B	PE:DRP/B	C:DRP/B	D:DRP
JFRingwald,sa <i>JFR</i>	JDixon-Herrity <i>JDH</i>	DNGraves <i>DNG</i>	DDChamberlain <i>DDC</i>	ABBeach <i>AB</i>
02/30/95	02/9/95	02/9/95	02/9/95	02/13/95

OFFICIAL RECORD COPY

FEB 13 1995

Wolf Creek Nuclear Operating Corporation

-4-

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan  
 Branch Chief (DRP/B)  
 Section Chief (RIII, DRP/3C)  
 SRI (Callaway, RIII)  
 Project Engineer (DRP/B)  
 Branch Chief (DRP/TSS)  
 A. B. Beach (D/DRP)

Resident Inspector (3)  
 DRSS-FIPB  
 RIV File  
 MIS System  
 Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME:r:\\_wc\wc419rp.jfr

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SRI:DRP/B	RI:DRP/B	PE:DRP/B	C:DRP/B	D:DRP
JFR <i>[Signature]</i> 01/30/95	JDixon <i>[Signature]</i> 02/9/95	DNGray <i>[Signature]</i> 02/9/95	DDChapman <i>[Signature]</i> 02/9/95	ABBeach <i>[Signature]</i> 02/13/95

OFFICIAL RECORD COPY