

RECEIVED SAFETY INSPECTION
NRC
REGION V

1. LICENSEE

CTI, Inc.
3512 International Way
Fairbanks, Alaska 99701

2. REGIONAL OFFICE

U. S. Nuclear Regulatory Commission
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

3. DOCKET NUMBER(S)

4. LICENSE NUMBER(S)

5. DATE OF INSPECTION

50-19202-2

August 9, 1988

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. _____ was not properly posted to indicate the presence of a _____, 10 CFR 20.203(b), (c), (d), (e) or 34.42.
- ☐ B. Containers located in _____ were not properly labeled to indicate the presence of radioactive material, 10 CFR 20.203(f)(1), or (f)(2).
- ☐ C. _____ of sealed sources were not performed at the proper frequencies, 10 CFR _____ License Condition Number _____.
- ☒ D. Records of transfer for two Campbell-Pacific gauges (S/N 7669 & 7670) were not properly maintained, 10 CFR 30.51(a) or License Condition Number _____.
- ☐ E. Documents were not properly posted or otherwise made available, 10 CFR 19.11.
- ☐ F. Reports or notifications of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
- ☒ H. 10 CFR 71.5 states, in part, that each licensee who transports licensed material outside the confines of its plant or other place of use, or who delivers licensed material to a carrier for transport, shall comply with the applicable requirements of the regulations appropriate to the mode of transport of DOT in 49 CFR Parts 170 through 189. 49 CFR 173.415(a) states, in part, that each shipper of a specification 7A package must maintain on file a complete documentation of tests and an engineering evaluation or ~~comparative~~ comparative data showing that the package is constructed in accordance with DOT design requirements.
- ☐ I. Contrary to the above requirements, at the time of the inspection, the documentation related to the above mentioned performance test had not been maintained.
- ☐ J. _____
- ☐ K. _____

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

Sandy U. Watson

197.98

Paul R Zurakowski

31 Aug 88

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

8809150057-NA1P