

APPENDIX A

NOTICE OF VIOLATION

Pennsylvania Power and Light Company  
Susquehanna Unit 1

Docket No. 50-387  
License No. NPF-14

As a result of the inspection conducted on October 3 - November 6, 1983, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violations were identified:

- A.1 10 CFR 50.55(d) requires that, at or about the time of completion of the construction of the facility, the applicant file any additional information needed to bring the original application for license up to date.

Contrary to the above, changes were made to the primary containment isolation actuation logic prior to the issuance of Operating License NPF-14 on July 17, 1982 and, as of October 21, 1983, the applicant had not filed the additional information.

This is a Severity Level IV violation (Supplement II).

- A.2 Technical Specification Surveillance Requirement 4.6.1.1.b requires that, at least once every 31 days, all primary containment penetrations not capable of being closed by automatic containment isolation valves (and required to be closed during accident conditions), be verified closed by valves, blind flanges, or deactivated automatic valves secured in position.

Contrary to the above, from May 1, 1983 to October 17, 1983, a period of 169 days, there was no closure verification for the drywell head seal valve; a valve which isolates a primary containment penetration not capable of being isolated by an automatic containment isolation valve.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Pennsylvania Power and Light is hereby required to submit to this office within 30 days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time. A written response is not required for violation A.2 because corrective actions have already been verified.

8401180257 840104  
PDR ADOCK 05000387  
PDR  
Q

APPENDIX B

NOTICE OF VIOLATION

Pennsylvania Power and Light Company  
Susquehanna Unit 1

Docket No. 50-387  
License No. NPF-14

As a result of the inspection conducted on October 3 - November 6, 1983, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 9, 1982 (47 FR 9987), the following violation was identified:

THIS SPACE WAS INTENTIONALLY LEFT BLANK. ORIGINAL  
VERSION CONTAINS SAFEGUARDS INFORMATION.

This is a Severity Level IV violation (Supplement III).

Pursuant to the provisions of 10 CFR 2.201, Pennsylvania Power and Light is hereby required to submit to this office within 30 days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.