

December 17, 1982

Mr. J. G. Keppler, Regional Administrator Office of Inspection and Enforcement, Region III U. S. NUCLEAR REGULATORY COMMISSION 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NOS. 50-266 AND 50-301

IE BULLETIN NO. 82-04

DEFICIENCIES IN PRIMARY CONTAINMENT

ELECTRICAL PENETRATION ASSEMBLIES

POINT BEACH NUCLEAR PLANT, NITS 1 AND 2

IE Bulletin No. 82-04 provided information about deficiencies in primary containment electrical penetration assemblies supplied by the Bunker Ramo Company. All recipients of the Bulletin were asked to review the information contained within for applicability to their facilities and to take appropriate action.

In accordance with IE Bulletin 82-04 we have checked the manufacturer of the containment electrical penetration assemblies utilized at Point Beach Nuclear Plant. We have determined that no Bunker Ramo penetration assemblies were ever installed at Point Beach either originally or during backfit and modifications. Further, no Bunker Ramo assemblies have been acquired as spares for future installation in any system at Point Beach. We, therefore, feel we have satisfied the requirements of IE Bulletin 82-04, and no further action is needed.

In order to help you evaluate the utility costs in implementing IE Bulletin 82-04, the staff time spent in preparing our written response was approximately four hours.

Very truly yours,

8212280361 821217 PDR ADOCK 05000266 Q PDR

Assistant Vice President

C. W. Fay

Copy to NRC Resident Inspector

Subscribed and sworn to before me this 17th day of December 1982.

Notary Public, State of Wisconsin.
My Commission expires July 1, 1984.

DEC 2 2 1982 IEII