



TESTWELL CRAIG
TESTING LABORATORIES, INC.

P.O. BOX 477 • 585 E. HARDING HIGHWAY, MAYS LANDING, NJ 08330
PHONE (609) 625-1700 • FAX (609) 625-6325

October 1, 1991

United States Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

Attention: Mr. Paul D. Swetland, Chief
Nuclear Materials Safety Section C
Division of Radiation Safety & Safeguards

RE: Docket No. 030-14353
License No. 29-18018-01

Gentlemen:

Pursuant to your letter, dated September 24, 1991, Testwell Craig Testing Laboratories, Inc. is herewith submitting the following information for your use and review:

Testwell craig fully understands the total aspects of our licensed activities and has attempted to fulfill these requirements in all instances.

We have been very active in training our employees and meeting with them to insure full compliance with the applicable regulatory statutes.

Despite our diligent efforts, the recent inspection by your staff indicated two deficiencies as follows:

1) Item A - Leak Testing of Sealed Sources

Gene Samuelson, our laboratory manager, has been designated by the company to insure that all sealed sources are leak tested twice per year.

Of the twelve portable sealed sources we have, four sealed sources had not been leak tested within the proper time frame.

These sealed sources were immediately leak tested along with our other units.

DIVISIONS IN LONG ISLAND CITY, NY • DANBURY, CONNECTICUT
OSSINING, NEW YORK • ALBANY, NEW YORK • MIAMI, FLORIDA • FAIRFIELD, NJ

9111110284 911001
REG1 LIC30
29-18018-01 PDR

-2-

To alleviate this problem from occurring in the future, we have placed "Leak Test Dates" on our calendars to insure compliance with the six month testing requirements.

2) Item B - Source Lock

All sealed sources assigned to our field personnel have storage locks.


After the incident of August 9, 1991, we reinventoried all sealed sources and purchased additional locks for these sealed sources. Same were again provided to all employees with sealed sources. Disciplinary action was also instituted against individual employees for not utilizing or losing their source locks.

We trust the information submitted is sufficient for your use and review.

As does the NRC, Testwell Craig feels strongly with complete compliance with the regulatory statutes of our license.

We will endeavor to completely comply with these regulations.

Very truly yours,



Michael W. Cannan
President

MWC/jdd