MATERIAL TRANSMITTED BET A TO CURTAINS



2.790 INFORMATION

NUCLEAR REGULATORY COMMISSION REGION V

1450 MARIA LANE, SUITE 210 WALNUT CREEK, CALIFORNIA 94596 RSB

Docket No. 70-1257

Exxon Nuclear Company 2101 Horn Rapids Road Richland, Washington 99352

Attention: Dr. R. Nilson, Manager

Corporate Licensing and Compliance

Gentlemen:

This letter refers to the routine Safeguards inspection of your activities authorized under NRC License No. SNM 1227 conducted by Messrs. C. A. Schwan and L. R. Norderhaug of this office on June 23, 1983. It also refers to the discussions of our inspection findings held by the inspectors with R. Miles and V. Collings on June 23, 1983.

The inspection included examination of activities related to physical protection against radiological sabotage and against theft of special nuclear material in accordance with applicable requirements of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials," your Security Plan, and license conditions pertaining to physical protection as described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with facility personnel and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of the findings of your safeguards and security measures are exempt from public disclosure; therefore, the enclosed inspection report will not be placed in the Public Document Room and will receive limited distribution.

MATERIAL TRANSMITTED HEREWITH CUNTAINS

8307110384 830701 PDR ADDCK 07001257 C PDR

1E05

MATERIAL TRANSMELTED REPLYMENT CONTAINS 2.790 INFORMATION

Exxon Nuclear Company

- 2 -

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

LeRoy R. Norderhaug, Chief

Safeguards and Emergency Preparedness

Branch

Enclosure:

Inspection Report

No. 70-1257/83-04 (IE-V-575)

bcc: RSB/Document Control Desk (RIDS), w/encl.

Distributed by RV:

JBM

State of Washington, w/encl without encl.

LEMB

RV 2 C. Schwan: dh 7/01 /83

L. Norderhaug
7/ /83

MATERIAL TRANSMITTE THE WITH CONTAINS 2.790 INFORMATION