

APPENDIX A
NOTICE OF VIOLATION

Arkansas Power & Light Company
Arkansas Nuclear One

Dockets: 50-313
50-368
License: DRP-51
NPF-6

Based on the results of an NRC inspection conducted during the period of July 11-15, 1983, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987, dated March 9, 1982, the following violations were identified:

1. Failure to Maintain Required Requalification Records

10 CFR Part 55, Appendix A, requires, in part, "Records of the requalification program shall be maintained for a period of two years from the date of the recorded event to document participation of each licensed operator and senior operator in the requalification program. The records shall contain copies of written examinations administered, the answers given by the licensee"

Contrary to the above, Arkansas Power & Light Company failed to maintain records of an examination given to Unit 2 licensed operators and senior operators on the classroom review of emergency procedures during the period of August and September 1981.

This is a Severity Level V Violation. (Supplement I.E) (50-368/8316-01)

2. Failure to Give General Employee Training to All Onsite Personnel

Technical Specifications for Arkansas Nuclear One, Units 1 and 2, require that there be a training program which meets or exceeds the requirements and recommendations of ANSI 18.1-1971. ANSI 18.1-1971 requires that General Employee Training be given to all persons "regularly employed in the nuclear power plant."

Contrary to the above, Arkansas Nuclear One Procedure 1063.07, "General Employee Training Program," Revision 1, dated February 8, 1983, limited full General Employee Training to Arkansas Power & Light Company employees, permanently employed at Arkansas Nuclear One, thereby excluding from full General Employee Training other site personnel working on site for a prolonged and indeterminate period.

This is a Severity Level IV Violation. (Supplement I.D) (50-313/8316-01 and 50-363/8316-02)

8308300622 830801
PDR ADOCK 05000313
Q PDR

3. Failure to Follow Procedures in Requalification Training

10 CFR 50, Appendix B, Criterion V, requires, in part, "Activities affecting quality shall be prescribed by documented instructions, procedures . . . and shall be accomplished in accordance with these instructions, procedures"

- a. Arkansas Nuclear One Procedure 1063.08, "Operations Training Program," Revision 2, dated May 31, 1983, requires, in part, "Pre-planned lectures will be scheduled to coincide with the current Operations rotation schedule. Formal lecture schedules will be generated by the Training Department, approved by the Operations Superintendents, and distributed to each licensed operator."

Contrary to the above, the Operations Superintendent for Unit 1 only approved the lecture schedule for one Operations rotation, (the first five-week training segment), for the 1982-1983 requalification training year. (50-313/8316-04)

- b. Arkansas Nuclear One Procedure 1063.08 also requires, in part, that licensed non-shift personnel participate in requalification training by, "Attendance of lectures in the categories in which a grade of less than 80% was scored on the previous annual written examination."

Contrary to the above, licensed, non-shift personnel did not, in at least two cases for each unit, attend lectures in the categories in which they had scored less than 80% on the previous annual examination." (50-313/8316-05 and 50-368/8316-05)

This is a Severity Level IV Violation. (Supplement I.D)

Pursuant to the provisions of 10 CFR 2.201, the Arkansas Power & Light Company is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated: August 1, 1983