

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi 0. BOX 1640, JACKSON, MISSISSIPPI 39205 A8:39 September 7, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File 0260/L-835.0 Special Report 83-012/1 -Update Peport - Fire Rated Seals Broken to Perform Planned Maintenance Activities AECM-83/0542

USNRO RE

This is an update to a previous report submitted on March 30, 1983, for the following event. From February 22, 1983, to March 16, 1983, numerous fire rated seals were opened to perform planned maintenance activities. Voluntary entry into Action (a) of Technical Specification 3.7.7 was made. The purpose of this update is to provide a revised estimated completion date for fire rated seals that have not been restored. The penetrations affected are listed on the attached page.

This condition has no affect on the health and safety of the public and does not constitute a threat to plant safety. The seals were opened to perform planned maintenance activities. An hourly fire watch is being conducted and will be maintained until work is complete. Estimated completion date for the remainder of the work tasks is now October 15, 1983. This is a Special Report submitted pursuant to Technical Specification 6.9.2.

Yours truly,

& HHobbs


L. F. Dale for Manager of Nuclear Services

EBS/SHH:sap Attachment

8309190160 830907 PDR ADOCK 0500041

cc: (See Next Page)

PDR



OFFICIAL COPY

Member Middle South Utilities System

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0542 Page 2

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Wighington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Attachment AECM-83/0542 Page 1 of 2

From February 22, 1983, to March 16, 1983, the following fire rated barriers were opened to perform planned maintenance activities. A restoration date is listed for the penetrations which have been restored. The remainder are expected to be restored by October 15, 1983.

El	Incident Date	Date Restored
Electrical Penetrations	Date	Date Restored
CE-82C	2/22/83	8/25/83
CE-201D	3/05/83	5/24/83
CE-202D-A	3/05/83	5/24/83
AE-279C	3/07/83	5/21/83
AE-177D	3/07/83	5/21/83
AE-61E	3/07/83	5/21/83
AE-11F	3/07/83	5/21/83
AE-1G	3/07/83	5/21/83
CE-268D	3/07/83	
CE-415B	3/07/83	
AE-30B	3/08/83	6/09/83
AE-82C	3/08/83	6/09/83
AE-91D	3/08/83	6/09/83
CE-82E	3/09/83	8/27/83
	3/09/83	0/2//00
AE-432B	3/09/83	
TE-14B	3/11/83	
AE-175B	3/12/83	
CE-26G	3/12/83	
CE-4C	3/12/83	
CE-272D	3/11/83	
CE-29G	3/11/83	
CE-31G	3/14/83	
CE-230DA		
AP-124C	3/16/83	
AC-85B	3/16/83	
AC-86B	3/16/83	
AC-84B	3/16/83	
AC-83B	3/16/83	
AC-46E	3/16/83	
AC-71D	3/16/83	
AC-90C	3/16/83	
AP-125C	3/16/83	(100 100
Equipment Hatch, Elev. 208	3/16/83	6/28/83
Fire Dams Opened	Date	
L092-LA21	3/11/83	
L043-LA45	3/14/83	
L043-LA58	3/14/83	
L090-LA1	3/14/83	
L089-LA18	3/14/83	
L095-LA58	3/14/83	

Attachment AECM-83/0542 Page 2 of 2

Fire Dams Opened	Date
L094-LA38	3/14/83
L050-LA26	3/14/83
L049-LA25	3/14/83
L012-LA46	3/14/83
L012-LA45	3/14/83
L012-LA58	3/14/83
L043-LA46	3/14/83
Cable Tray Covers Removed	Date
1AETWL01 - 1AETWL05	3/11/83
1AETWL15	3/11/83