

APPENDIX A  
NOTICE OF VIOLATION

Carolina Power & Light Company  
H. B. Robinson 2

Docket No. 50-261  
License No. DPR-23

As a result of the inspection conducted on June 11 - July 8, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.9.2.a.(3) requires that abnormal reactor coolant system pressure boundary degradation be reported within 24 hours by telephone and confirmed by telegraph, mailgram, or facsimile transmission to the Regional Administrator of Region II.

Contrary to the above, as of July 5, 1983, the abnormal degradation associated with the 'C' reactor coolant loop flow instrument had not been promptly reported.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: JUL 25 1983