

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

RECEIVED
NRC

1984 JAN 30 AM 8 50

January 23, 1984 REGION V/AR
ANPP-28657-BSK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Deficiency Evaluation Report 83-85
A 50.55(e) Evaluation Relating to Perimeter Microwave
Detection System For Units 1, 2, and 3 Contains A Generic
Manufacturing Defect
File: 84-019-026; D.4.33.2


Reference: Telephone Conversation between P. Narbut and K. Parrish on
December 23, 1983

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the
referenced telephone conversation, with a determination of reportability
to be made within thirty (30) days (January 24, 1984.)

The deficiency has subsequently been determined to be Not Reportable
under the requirements of 10CFR50.55(e), therefore no written report is
required. Necessary documentation of the evaluation will be maintained
in APS files.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President, Nuclear
ANPP Project Director

EEVB/TRB:ru

Attachment

cc: See Page Two

8402130285 840123
PDR ADOCK 05000528
S PDR

IE-27 110

Mr. T. W. Bishop
DER 83-85
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. R. Bynum
P. P. Klute
A. C. Cehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339