RECEIVED

Arizona Public Service Companyan 30 AM 8 50

P.O. BOX 21666 . PHOENIX, ARIZONA 85036

REGION VILLE

January 23, 1984 ANPP-28662-BSK/TRB

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director

Division of Resident

Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 83-72

A 50.55(e) Potentially Reportable Deficiency Relating To Undersized Welds In Unmit 1 Auxiliary Building Discovered By

NRC CAT Team

File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and R. Tucker on

October 26, 1983

(B) ANPP-28287, dated November 28, 1983 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by January 27, 1984.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by February 29, 1984, at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

50-528

E. E. Van Brunt, Jr.

Very truly yours,

AFS Vice President, Nuclear

ANPP Project Director

EEVB/TRB: ru

cc: See Page Two

Mr. T. W. Bishop DER 83-72 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

J. A. Roedel

D. B. Fasnacht

A. C. Rogers

B. S. Kaplan

W. E. Ide

J. Vorees

J. R. Bynum

P. P. Klute

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

G. A. Fiorelli

S. R. Frost

J. Self

D. Canady

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339