



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

February 3, 1984

W3K84-0241
Q-3-A35.07.92

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L letter W3K83-1974 dated December 15, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 92
"High Pressure Safety Injection System Performance"
Third Interim Report

The above referenced letter indicated submittal of an update or Final Report to the USNRC on February 1, 1984.

At the present time, corrective action, testing and engineering evaluation are completed. Review of supporting documentation is scheduled to be completed by mid February 1984.

A Final Report will be submitted to the USNRC on February 24, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:JC

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555
(15 copies)

8402140056 840203
PDR ADOCK 05000382
S PDR

IE-2710

Mr. J. T. Collins
February 3, 1984
W3K84-0241
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339