


POST OFFICE BOX 2951 · BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

Fe ruary 2, 1984 RBG- 16,926 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV. Office of Inspection and Enforcement 611 Ryar Claza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:



River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-103

Gulf States Utilities Company has not completed it's investigation of DR-103 concerning the lifting lugs on the containment dome. An interim or final status report will be provided by March 16, 1984.

Sincerely.

J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/je

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident aspector-Site

8402140369 840202 PDR ADOCK 05000458 S FUR