


THE CINCINNATI GAS & ELECTRIC COMPANY



CINCINNATI, OHIO 45201

September 21, 1983  
LOZ-83-0134

J. WILLIAMS, JR.  
SENIOR VICE PRESIDENT  
NUCLEAR OPERATIONS

Docket No. 50-358

U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Attention: Mr. J.G. Keppler  
Regional Administrator

Gentlemen:

RE: WM. H. ZIMMER NUCLEAR POWER STATION - UNIT 1  
10CFR50.55(e), ITEM S-10, MASONRY WALL  
CONSTRUCTION NOT PER DESIGN SPECIFICATION AND  
FSAR CRITERIA  
W.O. 57300, JOB E-5590, FILE NO. 956C, S-10

This letter constitutes an interim report concerning the subject condition initially reported to the Commission on May 13, 1983 as a potentially reportable deficiency under the requirements of 10CFR50.55(e). Based on a September 1, 1983 telephone conversation between W. Forney (NRC) and D. Stephenson (CG&E), an extension for submittal of this report was granted from our commitment date of September 12, 1983 to September 21, 1983.

As indicated in our previous report, LOZ-83-0047, dated June 13, 1983, the Quality Confirmation Program (QCP) is being expanded to include reinspection and verification of Category I Masonry Walls. CG&E and Sargent & Lundy are presently developing a reinspection program to ensure that the Masonry Walls will function as designed. The development of this program is expected to be completed by December 23, 1983 at which time a follow-up report will be submitted.

8309290040 830921  
PDR ADOCK 05000358  
S PDR

SEP 26 1983


IE 27  
10

Mr. J.G. Keppler  
Regional Administrator  
September 21, 1983  
LOZ-83-0134  
Page 2

We trust the above will be found acceptable as an interim report under 10CFR50.55(e).

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

By   
J. WILLIAMS, JR.  
SENIOR VICE PRESIDENT

DJS/sfr

cc: NRC Office of Inspection & Enforcement  
Washington, D.C. 20555  
NRC Senior Resident Inspector  
ATTN: T.P. Gwynn  
NRC Zimmer Project Inspector, Region III  
ATTN: E. R. Schweibinz