

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

Docket No. 50-329 Docket No. 50-330 September 23, 1983

Mr. D. B. Miller Site Manager P. O. Box 1963 Midland, MI 48640

Dear Mr. Miller:

SUBJECT: REMEDIAL SOILS WORK ACTIVITIES

The following critical work activities presently scheduled for the month of Sept.,1983 have been reviewed by our office. You are authorized to proceed with the work.

522550026 165052320 165052032 115150026 155052032 165053315 522550020 155053315 165054310 155052320 155054310

Should you have any questions regarding this matter, please call me at (312) 932-2635.

Sincerely,

John J. Harrison, Chief Section 2, Midland

Enclosure: Attachment A

cc: See Attached List

cc w/encl: DMB/Document Control Desk (RIDS) Resident Inspector, RIII The Honorable Charles Bechhoefer, ASLB The Honorable Jerry Harbour, ASLB The Honorable Frederick P. Cowan, ASLB The Honorable Ralph S. Decker, ASLB William Paton, ELD Michael Miller Ronald Callen, Michigan Public Service Commission Myron M. Cherry Barbara Stamiris Mary Sinclair Wendell Marshall Colonel Steve J. Gadler (P.E.) Howard Levin, TERA Billie P. Garde, Government Accountability Project Lynne Bernabei, Government Accountability Project

RALL D Landsman RBR Gardner

Harrison

cc w/encl: DMB/Document Control Desk (RIDS) Resident Inspector, RIII The Honorable Charles Bechhoefer, ASLB The Honorable Jerry Harbour, ASLB The Honorable Frederick P. Cowan, ASLB The Honorable Ralph S. Decker, ASLB William Paton, ELD Michael Miller Ronald Callen, Michigan Public Service Commission Myron M. Cherry Barbara Stamiris Mary Sinclair Wendell Marshall Colonel Steve J. Gadler (P.E.) Howard Levin, TERA Billie P. Garde, Government Accountability Project Lynne Bernabei, Government Accountability Project



Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

August 31, 1983

Mr J J Harrison Midland Project Section U S Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER GWO 7020
REMEDIAL SOILS WORK AUTHORIZATION
File: 0485.16 UFI: 42*05*22*04 Serial: CSC-6868
12*32

We have completed our review of the documents for the activity listed below. Based on our review, we concluded that we are ready to start the work:


522550026 Assembly and Wire Pump Control Panels

According to the NRC/CPCo Work Authorization Procedure, we request authorization for the above activity.

DBM/DWP/klm

2349130012

Doneld B Miller, Jr Site Manager Midland Project



Attachment A



Donald B Miller, Jr Site Manager Midland Project

Midland Project: PO Box 1963, Midland, MI 48640 • (517) 631-8650

August 22, 1983

Mr J J Harrison Midland Project Section U S Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDIAND ENERGY CENTER GWO 7020
REMEDIAL SOILS WORK AUTHORIZATION
File: 0485.16 UFI: 42*05*22*04 Serial: CSC-6858
12*32

We have completed our review of the documents for the activity listed below. Based on our review, we concluded that we are ready to start the work:

115150026 Remove 36" Casing and Backfill 42" Hole (Limited to upper According to the NRC/CPCo Work Authorization Procedure, we request steel lagging) authorization for the above activity.

DBM/DWP/klm

83\$839649 PDR



J A Mooney

Executive Manager

Midland Project Office

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0774

August 12, 1983

Mr J J Harrison Midland Project Section U S Nuclear Regualtory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDIAND ENERGY CENTER GWO 7020
REMEDIAL SOILS WORK AUTHORIZATION
File: 0485.16 UFI: 42*05*22*04 Serial: CSC-6850

We have completed our review of the documents for the activity listed below. Based on our review, we submit the following for work authorization:

GENERAL TEMPORARY DEWATERING

← 522550020 Repair Six (6) Existing Observation Wells (WB-1, WP-2, COE-10, PD-18, W-2, PD-38)

Note: There were duplicate numbers, including the above number, in last month's Work Activities List (CSC-6798). The following changes will be made to correct the duplication:

522550020 Excavate, Install and Backfill Header Piping, Electrical Conduit, and Pumps (Includes Equipment Slabs and Metering Pits. [See Page 11]).

This number will be changed to be 522550021.

522550025 Assembly and Wire Pump Control Panels. This number will be changed to be 522550026.

These two activity number changes will be made on the next issue of the activity list.

JAM/AEB/klm

8348224234



J A Mooney

Executive Manager

Midland Project Office

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0774

September 7, 1983

Mr J J Harrison Midland Project Section U S Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER GWO 7020
REMEDIAL SOILS WORK AUTHORIZATION
File: 0485.16 UFI: 42*05*22*04 Serial: CSC-6878
12*32

We have completed our review of the documents for the activities listed below. Based on our review, we concluded that we are ready to start the work:

-402550525 - Temporary backfill new pipe (Train A)

-203150165 - Fill SWPS chambers with water to el. 622 (±5')

~402550446 - Excavate existing pipe (Train B)

~402550562 - Temporary backfill new pipe (Train B)

155052320 - Drift from KC3 to 13 feet east of KC4

165052320 - Drift from KC10 to 9 feet west of KC9

155052032 - Finger drift to KC4

155053315 - Excavate Pier KC4

155054310 - Install and load Pier KC4

165052032 - Finger drift to KC9

165053315 - Excavate Pier KC9

165054310 - Install and load Pier KC9

- 207050601 - SWPS-Install four (4) additional piezometers

Also, a number of activity authorizations have passed the 90 day expiration limit. In accordance with the Work Authorization Procedure, we request re-authorization of the following activities:

TRAIN B OF SERVICE WATER PIPE REPLACEMENT

402550550 - Remove existing pipe

402550560 - Install new pipe and expansion coupling

402550561 - Hydro test new pipe

402550508 - Perform profiling and ovality check on new piping

JAM/AEB/klm 8349134378