

The information on this page is considered to be appropriate
for public disclosure pursuant to 10 CFR 2.790.

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION V

Report No. 110-03133/83-01 (IE-V-587)

Docket No. 110-03133

License No. XSNM 02027

Safeguards Group IX

Licensee: Marubeni America Corporation
650 California Street
San Francisco, California 94103

Facility Name: All Trans Express

Inspection at: 737 Bay Street, Oakland, California

Inspection Conducted: September 14, 1983

Date of Last Material Control and Accounting Inspection: April 6, 1983

Type of Inspection: Material Control and Accounting, Safeguards

Inspectors:

G. B. Nelson
G. B. Nelson, Chemist

9-28-83
Date Signed

A. V. Wieder
A. V. Wieder, Safeguards Auditor

9/28/83
Date Signed

B. L. Brock
B. L. Brock, Fuel Facilities Inspector

9/27/83
Date Signed

P. R. Zurakowski
P. R. Zurakowski, Radiation Specialist

9/28/83
Date Signed

Approved by:

LeRoy R. Worderhaug
LeRoy R. Worderhaug, Chief, Safeguards and
Emergency Preparedness Branch

9/28/83
Date Signed

Inspection Summary:

Areas Inspected: Verified shipping drum identification and tamper seal numbers to the shipment packing lists; confirmed gross drum count; shipping container and tamper seal integrity; compared quantitative data with amounts authorized by NRC export license as shown in the shipping papers; monitored external radiation level and wipe checked each drum surface for detectable contamination. This inspection involved 9 hours of on-site time by four NRC inspectors.

Results: No items of noncompliance were noted.