

Carolina Power & Light Company P 22 A10: 48

H. B. ROBINSON STEAM ELECTRIC PLANT POST OFFICE BOX 790 HARTSVILLE, SOUTH CAROLINA 29550 SEP 1 9 1983

Robinson File No: 13510C

Serial: RSEP/83-1204

Mr. James P. O'Reilly Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, N. W., Suite 3100 Atlanta, Georgia 30303

> H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261 LICENSE NO. DPR-23 PROMPT NOTIFICATION - GASEOUS RELEASE

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for H. B. Robinson Steam Electric Plant, Unit No. 2, the following event is reported.

At approximately 1800 hours on September 16, 1983, it was determined that the Technical Specification instantaneous release limit for radioiodine was exceeded during that afternoon. Investigation of this event is continuing in an effort to determine the source of the radioiodine. No additional releases, greater than the normally expected levels, have occurred.

This event was reported on the evening of September 16, 1983, to the NRC, Region II, and Mr. G. P. Beatty, Jr., Manager - Robinson Nuclear Project Department.

Very truly yours,

Kellingan R. E. Morgan

General Manager H. B. Robinson SEG Plant

TE 22

HTC/bss

cc: G. P. Beatty, Jr. S. P. Weise

PDR ADOCK 05000261 310030426 8309