

POST OFFICE BOX 2951 + BEAUMONT, TEXAS 77704 AREACODE 409 838 6631

> February 17, 1984 RBG-17,064 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011



IE-2710

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Final Report/DR-103

Gulf States Utilities Company has completed its investigation of DR-103 concerning the lifting lugs on the containment dome and has determined this condition is not reportable under 10 CFR 50.55(e).

Sincerely,

J. E. Berher

J. E. Booker Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8402280486 840217 PDR ADOCK 05000458 S PDR