CONSUMERS POWER COMPANY MIDLAND ENERGY CENTER

50-329

Transmittal No: CSC- 7358

Date: February 22, 1984

To: Stone & Webster P O Box 1963 Midland, MI 48640

Attached Is:	Partial Response To	0
	X Complete Response	Co
	For Your Information	on
	Other	

RA A	CIPAL ST	AFF	
D/RA	DE		
AZRA	OR ISP	- Sellinger-Springeren	
RC	DRMA		
PAO	SCS T	1	ougt=
SGA	ML		Curp' -
ENF	File	200	

Description:

Meeting Note, Report No. 29 - The arc strike issue has been resolved per SCN 14001 to specification C-304, copy attached.

NIR Signature: Mul

cc: JGKeppler, NRC Region III w/a
JJHarrison, NRC Region III w/a
RJCook, NRC Site w/a
RAWells, MPQAD w/a
BHPeck, MEC w/a
NIReichel, MEC w/a
DDJohnson, MEC w/a

8402290155 840222 PDR ADDCK 05000329 S PDR

FEB 2 7 1984

I 801 1

Bechtel Power Corporation

Post Office Box 2167 Midland, Michigan 48640 February 21, 1984



Consumers Power Company P.O. Box 1963 Midland, Michigan 48640

Attention: D. L. Quamme Site Manager

Midland Plant Units 1 & 2
Bechtel Job 7220
STONE & WEBSTER MEETING REPORT
22-NCR C-00708
BCCC-9048

Dear Mr. Quamme:

This is Construction's final response to NCR C-00708 (Arc Strike).

SCN 14001 to Specification C-304 (attached) has been issued providing retroactive inspection criteria clarification.

Based on the retroactive clarification NCR C-00708 has been voided by MPQAD-QC, therefore, this issue is closed.

Very truly yours,

G. A. Hierzer Site Manager

GAH/JER/ajd

Attachment: Spec. C-304

Written Response Requested: No

SCN NO. 14001 DATE 2/8/84 Page 1 of 2

SPECIFICATION CHANGE NOTICE

A.	SPECIFICATION NO. 7220-C-304(Q) REV. 14 DATE 1/27/84
B.	SPECIFICATION TITLE FIELD FARRICATION, REPAIR AND ERECTION OF STRUCT. STE AND MISC. MET
C.	CHANGE REQUESTED BY: DICLENT MENGINEERING MILE DI VENDOR/CONTRACTOR
D.	CHANGE PREPARED BY STEVE WUTHRICH DATE 2/8/84
E.	DESCRIPTION OF CHANGE
	REVISED AS SHOWN ON THE FOLLOWING PAGE UNCONTROLLED
	MOT TO BE USED PECELVED FEB 0 9 1984
	BECHIEL POWER CORP
F.	REASON FOR CHANGE CLARIFICATION AND ADDITION TELEVISION CLARIFICATION AND ADDITION
	OF REQUIREMENTS
G.	EFFECTIVITY OF CHANGE RETROACTIVE
н.	INSTRUCTIONS REGARDING USED MATERIAL/EQUIPMENT WA Incorporates the following
	change documents:
	7220-492 3/83
1.	APPROVAY SIGNATURES 1 V La face 2/8/04 Star hattrich 2/8/84
	Sur for PL: Roquestly 2/8/84 me South FOR R.C. HOUSE 2/8/84
	Mike Malle 2/8/84 JMUSA V. Doiet 2/8/84
1.	INCORPORATEDIN SPEC
	REV GAOLP SUPERVISOR DATE

ANG-072175 Rev 1/60

SPECIFICATION 1220-6-304(Q) SCN NO. 2/8/89 14001 Page 2 of 2

- 6.3.9 Are strikes are acceptable, providing the cruters do not contain crucks as determined by visual examination. Weld metal or metallic inclusions located in the arc strike cruter do not require removal to facilitate visual examination.
- 6.3.6 But welds shall be slightly convex, of uniform height, and shall be full penetration unless otherwise shown. Weld reinforcement for butt welds shall not exceed 3/16 inchuncontrolled

 NOT TO BE USED FOR CONSTRUCTION