

APPENDIX A

NOTICE OF VIOLATION

Public Service Company of New Hampshire
Seabrook Station, Unit 1

Docket No. 50-443
License No. CPPR-135

As a result of the inspection conducted on December 19-22, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), published in Federal Register on March 9, 1982 (47 FR 9987) the following violation was identified:

10 CFR 50, Appendix B, Criterion X, requires a program for inspection... to verify conformance with the documented instructions, procedures, and drawings for accomplishing the activity. United Engineers and Constructors (UE and C) installation drawing M-300230 sheet 27 required that field wiring be securely clamped by connectors that were bolted to the equipment to support a seismic event.

Contrary to the above, as of December 22, 1984, the installation of field safety-related wiring harnesses were not being terminated in electrical equipment as required by drawing M-300230, with bolted tie connectors but instead were tied to a glued type of connector for termination.

This is a Severity Level IV violation. (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Public Service Company of New Hampshire is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.