

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER
MANAGER

DEPARTMENT OF NUCLEAR PLANT OPERATIONS
NUCLEAR POWER GENERATION

February 29, 1984

PGandE Letter No.: DCL-84-079

Mr. John B. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368


Re: Docket No. 50-275, OL-DPR-76
Diablo Canyon Unit 1
Special Report - Inoperable Fire Pump, SR 84-02

Dear Mr. Martin:

Pursuant to Section 6.9.2 of Appendix A of the Diablo Canyon Unit 1 Operating License, and as specifically required by Technical Specification 3.7.9.1, this Special Report is submitted concerning the inoperability of Fire Water Pump No. 0-1 for more than seven (7) days.

On January 23, 1984, at 1015 PST, Fire Water Pump No. 0-1 was declared inoperable after the pump motor circuit breaker tripped following several motor automatic starts while filling a section of the fire main header. Investigation determined that the cause of the breaker trip was frequent motor starts in a short time period. A surveillance test was conducted, and Fire Water Pump No. 0-1 was returned to service on January 31, 1984 at 1237 PST.

Sincerely,



cc: G. W. Knighton

Director, Office of Management Information
and Program Control

Service List

8403150025 840229
PDR ADOCK 05000275
S PDR

IE-2210