

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

October 21, 1983

TELEPHONE
(704) 373-4531

83 OCT 31 4 9:31

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Units 1 and 2
Docket Nos. 50-369 and 50-370
LER/RO-369/83-86 and 370/83-54

Dear Mr. O'Reilly:

Reportable Occurrence Reports RO-369/83-86 and 370/83-54 were to have been submitted by October 21, 1983. These 30 day Reportable Occurrences (pursuant to T.S. 6.9.1.11) concern degradation of the spray and/or sprinkler systems (T.S. 3.7.10.2) which were discovered on September 23, 1983. However, investigation of the incidents and preparation of the reports are incomplete at this time. The reports will be submitted by November 4, 1983.

Very truly yours,

H.B. Tucker

Hal B. Tucker

PBN:jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

ORIGINAL COPY

8311020259 831021
PDR ADOCK 05000369
S PDR

IE 22
1/0