

POST OFFICE BOX 2951 \* BEAUMONT. TEXAS 77704


AREACODE 409 838 6631

October 24, 1983 RBG-16227 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Final Report/DR-127



Gulf States Utilities Company has completed its investigation of DR-127 concerning the unauthorized wiring of a breaker and determined this condition does not meet the criteria for reportability under 10CFR50.55(e).

Sincerely,

J. E. Booker

Manager-Engineering,

Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8311030144 831024 PDR ADDCK 05000458 S PDR