


REC-12:01
B. 3/24/75

file



ROCHESTER GAS AND ELECTRIC CORPORATION • 69 EAST AVENUE, ROCHESTER, N.Y. 14649

TELEPHONE
AREA CODE 716 548-2700

Glenn Station
March 24, 1975

Mr. James P. O'Reilly
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

50-244

Subject: Abnormal Occurrence #75-07: Abnormal Degradation of Steam Generator Tubes

Dear Mr. O'Reilly:

This is to confirm my phone call to Mr. John Hannon this morning to report Abnormal Occurrence #75-07 at Glenn Station.

At the beginning of our refueling shutdown, an eddy current testing program was carried out for the "A" and "B" Steam Generators. Preliminary results from the test indicate that 10 tubes in the "A" Steam Generator hot leg and 12 tubes in the "B" Steam Generator hot leg indicated tube wall thinning of 50% or greater.

Very truly yours,

Charles E. Platt
Charles E. Platt
Superintendent

CEP:fah

cc: Mr. G. J. Swarthout, RGE Corp.
Mr. L. D. White, Jr., RGE Corp.

8304050643 750407
PDR ADOCK 05000244
S PDR