

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1			-					-		4	1	1	1	1	0	3				
7	8	9				14	15								25	26					30	31	32			

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE							
01		M	1	L	L	0	5	0	-	0	2	2	0	0	4	2	3	7	6	0	5	2	1	7	6
7	8	57	58	59	60	61							68	69					74	75					80

[illegible]

02	During surveillance testing 02-13B a switch used for turbine auticipatory trip bypass	80
03	reactor scram was found to actuate at 364 psig rather than the required 355 + 5 psig.	80
04	Plant was operating above point thus required action would occur if required.	80
05		80
06		80
	RO 76-19	

SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 I A E I N S T I R U N B O 7 0 -

7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08	Setpoint drift switch was recalibrated and placed back in service.	
09		50
10		80

11	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		80
7 8	C		0 6 0				b				
	9		10 12		13		44 45		46		80
FORM OF ACTIVITY RELEASED											
12	CONTENT OF RELEASE		AMOUNT OF ACTIVITY						LOCATION OF RELEASE		
7 8	Z		Z		N/A						
	9		10 11		44		45				

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	2	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A

OFFSITE CONSEQUENCES probable

15	NONE
7 8 9	

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	6	3	N/A

PUBLICITY

17	NONE	PDR ADDUCK 030000Z PDR
7 8 9		

ADDITIONAL FACTORS

13 No hazard to plant or general public.

19 |

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 25, 1976

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

Enclosed please find LER Reports (76-19, 76-20, & 76-21) for
Nine Mile Point Unit 1. These reports are in the acceptable format
as required and as a point of clarification and due to the previously
submitted type T reports on fish impingement, the numbering does not
follow in chronological order. This system is being changed to pre-
vent this problem in the future.

Very truly yours,

Original Signed by R.R. Schneider


R.R. Schneider
Vice President
Electric Operations

TJD/aih

Enc. 3 copies

CC: K.R. Goller (30 copies)



COPY SENT REGION 

5419