

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-1531

April 25, 1984

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4

Re: Catawba Nuclear Station
Docket Nos. 50-413 and 50-414

Dear Mr. Denton:

Section 7.3.2.2 of the Catawba Safety Evaluation Report discusses Confirmatory Item 26, Compliance with IE Bulletin 80-06. This bulletin requests a review of the ESF systems to verify that no device will change position solely because of the reset of the actuation signal. Such a review was performed and documented for the Staff. Further verification that the installed instrumentation and controls are in compliance with the requirements of IE Bulletin 80-06 is provided during pre-operational test TP/1/A/1200/03B, "Engineered Safeguards Feature (ESF) Test." Testing of Train A has been completed and this function was verified for equipment that was operated by an ESF signal. Train B testing is scheduled for April 29, 1984. The completed procedure will be available after this date at the Catawba site for review by the NRC.

Very truly yours,



Hal B. Tucker

ROS/php

cc: Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

NRC Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

Mr. Jesse L. Riley
Carolina Environmental Study Group
854 Henley Place
Charlotte, North Carolina 28207

*13001
1/0*

8404300159 840425
PDR ADOCK 05000413
E PDR