

February 11, 1971

*Trans
copy in file
some
long
D.L.*

NOTE TO: Dr. Peter A. Morris

I called Mr. George Kinsman to express to him our concerns with the repair procedure of the containment dome for Unit No. 3. I also expressed to him that we had additional questions that needed answering on the work, but he felt that they could handle these in a reasonably short period of time.

I went through the two alternatives that had been previously discussed with the Task Force and gave him a brief run down on what they represented and indicated to him that we should establish a meeting next week to attempt to get this matter resolved. I also indicated to him that they may wish to propose an alternative that would require our review, but that this will be discussed at the meeting.

I informed him that Commissioner Ramey would be in Miami this weekend, and if so, he would probably contact him or visit the Turkey Point site and also that the Commission was also aware of these alternatives and the problem associated with the repair of the containment dome.

I have expressed to him that it would be our desire that they do not place concrete until we have resolved these issues and indicated that he would do it on a voluntary basis. He also stated that the ACRS had also expressed the same concern and he remembered the discussion with the Committee whether or not to pour concrete and he indicated that it could be interpreted that way. He stated that they would not place any concrete until the matter was adequately resolved with the staff and ACRS.

Charles G. Long
Charles G. Long, Chief
PWR Project Branch No. 2
Division of Reactor Licensing

cc: P. Check
R. C. DeYoung
F. Schroeder
C. Long
PWR-2 Reading

50-250, Incident

*LOZ
RWC-2/18
OD 2/2
JBN-2/18*

8305190203 710319
PDR ADDCK 05000250
A PDR

Cy sent Reg II