

DIVISION OF COMPLIANCE MONTHLY REPORT, JUNE 1969

50-220/251
Florida Power and Light Company - Turkey Point Units 3 and 4 - A routine inspection of site construction activities was conducted on May 21-23. Cement grouting of concrete voids in the Unit 3 containment building mat was complete. Because cracks up to 0.012 inches wide were observed in each of the grouted areas, ultrasonic testing of the repaired areas was conducted on May 24. Test results will be reviewed during the next inspection.

X- Inspection folder

8305200156 700209
PDR ADOCK 05000250
A PDR