

Commonwealth Edison Company


ONE FIRST NATIONAL PLAZA ★ CHICAGO, ILLINOIS

Address Reply to:

POST OFFICE BOX 767 ★ CHICAGO, ILLINOIS 60690

July 6, 1970

Dr. Peter A. Morris, Director
Division of Reactor Licensing
U.S. Atomic Energy Commission
Washington, D.C. 20545



Subject: Additional Information Relative to
Provisional Operating License DPR-19 for
Dresden Unit 2

Dear Dr. Morris:

The purpose of this letter is to provide you with information concerning recent operational difficulties on Dresden Unit 2 and our proposed corrective actions. This information has been requested in your letter dated June 18, 1970 which responded to our proposed Change No. 2 to Appendix A of DPR-19.

Attached hereto is Exhibit I containing our evaluation of the following operational difficulties:

1. The rapid depressurization incident on June 5, 1970;
2. Main steam line isolation valves; and
3. Excessive hydraulic forces in the high pressure coolant injection system steam line.

An investigative program on unexplained fuel failures and excessive control rod scram times is in progress. The results of this program will be submitted when it is completed.

In addition to three signed originals, 19 copies of this information are also submitted.

Very truly yours,

Byron Lee Jr.

Byron Lee, Jr.
Assistant to the President

SUBSCRIBED and SWORN to
before me this 14 day
of July, 1970.

Notary Public
Notary Public

COPY SENT REGION

JUL 6 1970

~~02300~~

See: "Application" folder for attachments