

POINT BEACH NUCLEAR PLANT

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH AUGUST - 1991

Docket No. 50-301
 Unit Name Point Beach, Unit 2
 Date October 3, 1991
 Completed By D. C. Peterson
 Telephone No. 414/755-2321, Ext. 361

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report No.	System Code ⁴	Component Code ⁵	Cause and Corrective Action To Prevent Recurrence
1	910928	S	70	C	1				Scheduled refueling and maintenance outage, U2R17. Major work items include inspection and eddy current testing of steam generators, installation of full flow test lines for residual heat removal, safety injection and containment spray pumps, and increase of the steam-driven auxiliary feedwater pump mini-recirculation line.

¹F: Forced
¹S: Scheduled

²Reason:
 A - Equipment Failure (explain)
 B - Maintenance or Testing
 C - Refueling
 D - Regulatory Restriction
 E - Operator Training &
 Licensing Exam
 F - Administrative
 G - Operational Error (explain)
 H - Other (explain)

³Method:
 1 - Manual
 2 - Manual Scram
 3 - Automatic Scram
 4 - Continuation of
 Previous Shutdown
 5 - Reduced Load
 6 - Other (explain)

⁴Exhibit G - Instructions
 for preparation of
 data entry sheets
 LER file (NUREG-0161)

⁵Exhibit I - Same Source