

## **PUBLIC** SERVICE INDIANA

S. W. Shields Senior Vice President -Nuclear Division

October 13, 1983 S83-07 SVP-0134-83

Mr. James G. Keppler, Regional Administrator U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Docket Nos.: STN 50-546 STN 50-547 Construction Permit Nos.: CPPR - 170 CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2

Dear Mr. Keppler:

On February 28, 1983, Mr. L. G. Yeager of Public Service Company of Indiana, Inc. (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). A PSI audit of the site HVAC contractor, Pullman Construction Industries, Inc. (PCI), resulted in a number of findings which indicate that PCI has not adequately implemented their quality assurance program. It is conceivable that nonconforming conditions could exist and had they gone uncorrected, could have adversely affected the safe operations of the plant.

PCI has responded to the audit findings and PSI has accepted, subject to verification of the corrective action, PCI's dispositions. The disposition of some findings requires reinspection of materials. This reinspection is continuing at this time. A further report will be filed on or before February 10, 1984. This letter is intended to fulfill the requirements of an interim report as required by 10 CFR 50.55(e). If you have any questions regarding this matter, please contact me at your convenience.

Sincerely

S. W. Shields

SWS/LGY/bak

8310210025 831013 PDR ADDCK 05000546 OCT 17 1983



Letter: J. G. Keppler

-2- October 13, 1983 S83-07 SVP-0134-83

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. E. Konklin J. F. Schapker