Parameter, Inc. Consulting Engineers • Design - Analysis - Development 13545 WATERTOWN PLANK ROAD, ELM GROVE, WISCONSIN 53122 786-7580 June 25, 1971 United States Atomic Energy Commission Division of Compliance Washington, D. C. 20545 Copies: Distribution: Mr. L. Kornblith, Jr. Asst. Director for Technical Programs D. L. Pomeroy (1) Reference: AEC Contract No. AT(11-1)-1658, Task A Consulting Services Assignment No. DC-89 PAR: 70-71 A Gentlemen: Enclosed for your information and reference are two (2) copies of the following report prepared by Dr. S. Weiss: "Report on Inspection of Leaks and Cracks in the (A) Steam Generator at H. B. Robinson II" - Report No. DC-89 dated June 23, 1971 Very truly yours, PARAMETER, Inc. 8403090401 710617 PDR ADOCK 05000261 L. C. Campbell lcc Enclosures cc: 70-71 A file DC-89 file Dr. S. Weiss