DUKE POWER COMPANY
CRISIS MANAGEMENT
IMPLEMENTING PROCEDURES

December 11, 1991

TABLE OF CONTENTS

Volume 2

Tab	Procedure Description
CMIP-8	Oconee Crisis Phone Directory (Rev. 32)
CMIP-9	McGuire/Catawba Crisis Phone Directory (Rev. 40)
CMIP-10	Emergency Classification - Catawba (Rev. 4)
CMIP-11	Emergency Classification - McGuire (Rev. 13)
CMIP-12	Reserved for Future Use
CMIP-13	Notifications to States and Counties from the Crisis Management Center (Rev. 24)
CMIP-14	Crisis Management Data Transmittal System Access for Offsite Agencies - (Rev. 3)
CMIP-15	Oconee CMC Initial Activation - (Rev. 0)
CMIP-16	Crisis Management Data Transmittal System Access from the Crisis Management Center - (Rev. 11)
CMIP-17	Reserved for future use
CMIP-18	Maintaining Emergency Preparedness (Rev. 5)
CMIP-19	Communications Test for McGuire/Catawba CMC (Rev. 17)
CMIP-20	Communications Test for Oconee CMC (Rev. 11)
CMIP-21	Quarterly Tentory Equipment Check (Rev. 37)
CMIP-22	Telephone Number Updates (Rev. 3)

CRISIS MANAGEMENT IMPLEMENTING PROCEDURE

CMIP-11

Classification of Emergency for McGuire Nuclear Station

Rev. 13

December 11, 1991

Approved By

Date

12/18/91

CMIP-11 CLASSIFICATION OF EMERGENCY FOR MCGUIRE NUCLEAR STATION

1.0 SYMPTOMS

1.1 Notification of Unusual Event

- 1.1.1 Events are in progress or have occurred which indicate a potential degradation of the level of safety of the plant.
- 1.1.2 No releases of radioactive material requiring offsite response or monitoring are expected unless further degradation of safety occurs.

1.2 Alert

- 1.2.1 Events are in progress or have occurred which involve an actual or potential substantial degradation of the level of safety of the plant.
- 1.2.2 Any releases are expected to be limited to small fractions of the EPA Protective Action Guideline exposure levels.

1.3 Site Area Emergency

- 1.3.1 Events are in process or have occurred which involve actual or likely major failures of plant functions needed for protection of the public.
- 1.3.2 Any releases are not expected to exceed EPA Protection Action Guideline exposure levels except near the site boundary.

1.4 General Emergency

- 1.4.1 Events are in process or have occurred which involve actual or imminent substantial core degradation or melting with potential for loss of containment integrity.
- 1.4.2 Releases can be reasonably expected to exceed EPA
 Protective Action Guideline exposure levels offsite for
 more than the immediate site area.

2.0 IMMEDIATE ACTIONS

2.1 Compare actual plant conditions to the Emergency Action Level(s)
listed in Enclosure 4.1 then declare the appropriate Emergency Class
as indicated.

If a change in the emergency class is made, perform steps 2.2, 2.3, and 2.4 below.

2.2 Instruct the State/County Communicator to notify the state(s) and counties per CMIP-13 of any change in the emergency class. If the emergency class is SITE AREA EMERGENCY or GENERAL EMERGENCY, determine protective action recommendations per CMIP-1 and transmit these recommendations.

NOTE: Notifications to the state(s) and counties must be made within 15 minutes whenever there is a change in the emergency classification.

2.3 Announce the change in the emergency class to all CMC personnel and to the Emergency Coordinator at the TSC.

3.0 SUBSEQUENT ACTIONS

3.1 To de-escalate the Emergency, compare plant conditions to the Initiating Conditions of Enclosure 4.1. To terminate the emergency, refer to the Termination Criteria in Enclosure 4.3.

Notify state(s), counties, and NRC by verbal summary of any reduction or termination in the emergency class followed by a written summary within eight (8) hours.

4.0 ENCLOSURES

4.1. Emergency Event List for Emergency Classes

Event No.	Page(s)
4.1.1 Primary Coolant Leak	1-3
4.1.2 Fuel Damage	4-5
4.1.3 Steam System Failure	6-7
4.1.4 High Radiation/Radiological Effluents	8-10
4.1.5 Loss of Shutdown Function	11-15
4.1.6 Loss of Power	16-17
4.1.7 Fires and Security Actions	18-19
4.1.8 Spent Damage	20-22
4.1.9 Natural Disasters and Other Hazards	23-24
4.1.10 Other Abnormal Plant Conditions	25-29

- 4.2 Engineered Safety Features
- 4.3 Termination Criteria

MCGUIRE BUCLEAR STATION EMERGENCY ACTION LEVELS EVENT \$ 4.1.1 PRIMARY COOLANT LEAK

CMIP-11

PAGE 1 OF 29

GENERAL EMERGENCY

MOTIFICATION OF UNUSUAL EVENT

1. Any #C system leakage greater than Tech Spec

 Greater than 1 gpm unidentified NC system leakage in modes 1-4.

limits in Modes 1-4.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.6.2.

 Greater than 10 grm identified NC system leakage in modes 1-4.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.6.2.

 Greater than 500 gpd tube leakage in any S/G in modes 1-4.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.6.2.

1. Any MC system leakage greater than 50 qpm

in Modes 1-4.

THRAITA

 NC system leakage greater than 50 gpm in modes i-4.

AND

NC subcooling greater than 0 Deg. F.

AND

Leak cannot be isolated within 15 minutes.

- s/G tube leak with loss of offsite power.
- S/G tube leak greater than 10 gpm

AND

NC subcooling greater than 0 Deg. F.

AND

Both Unit related main bus lines deenergized. Any MC system leakage resulting in loss of subcooling in Modes 1-4.

SITE AREA ENERGKECY

 Si actuated or required in Modes 1-4

AND

Existing NV, WI and ND flow cannot maintain NC subcooling greater than 0 Deg. F.

- S/G tube leak with an unisolable secondary (main steam or feedwater) break outside containment.
- Primary to secondary leakage greater than 50 gpm

AND

Unisolable secondary (main steam or feedwater) line break on the ruptured S/G outside containment

- 1. Any LOCA with failure of BCCS
- * LOCA with failure of both trains of BCCS injection

AND

NC subcooling cannot be maintained greater than 0 Deg. F.

 LOCA with failure of both trains of ECCS recirculation when recirculation required.

AND

NC subcooling cannot be maintained greater than O Deg. F.

LOCA

AND

Plant conditions require entry into BP/1 or 2/A/5000/12.1 (Response to Inadequate Core Cooling) 1

MCGUINE WICLEAR STATION EMERGENCY ACTION LEVELS EVENT # 4.1.1 PRIMARY COOLANT LEAK

MOTIFICATION OF UNUSUAL EVENT

 Greater than 1 gpm total tube leakage in all S/G's in modes 1-4.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.6.2.

 Any NC system pressure boundary leakage in modes 1 4.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.6.2.

 Greater than 1 gpm leakage from any NC pressure isolation valve at 2235 psig in modes 1-4.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.6.2.

ALERT

- S/G tube leak with an unisolable secondary line break outside containment.
- s/G tube leak greater than 10 gpm but less than 50 gpm;

AND

NC subcooling greater than 0 Deg. F

AND

Unisolable secondary (main steam or feedwater) line break outside containment on the ruptured S/G.

 Unisolable secondary(main steam or feedwater) line break outside containment

AND

Field monitoring teams detect activity at the protected area fence at greater than or equal to 2 mRem/hr whole body.

END

3. Steam generator tube leak with secondary line break inside

SITE AREA EMERSIONCY

containment and indication of fuel damage.

• Primary to secondary leakage greater than

50 gpm

AND

Unisolable secondary (main steam or feedwater) break inside containment on the ruptured S/G

AND

Fuel clad failure greater than 5% per Chemistry analysis (or valid reading on EMF-51a or 51b of 117 R/hr).

END

GENERAL. ENRHGENCY

- LOCA with initially successful BCCS followed by failure of BCCS heat sink and failure of containment heat resoval.
 - LOCA

AND

Loss of recirculation heat

AND

Loss of containment spray heat sink

END

1

MCGUIRE RECLEAR STATION EMERGENCY ACTION LEVELS EVENT # 4.1.1 PRIMARY COOLANT LEAK CMIP-11 ENCLOSURE 4.1 PAGE 3 OF 29

MOTIFICATION OF UNUSUAL EVENT ALERT

SITE AREA EMERGINCY

GENERAL EMERGENCY

* Greater than 40 gpm controlled NC system leakage at 2235 paig in modes 1-4.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.6.2.

- Any anisolable MC syntem leakage greater than 50 gpm in Modes 5 and 6.
- 3. Failure of an unisolable par PORV or safety valve to close following a reduction of MC pressure.

MOTIFICATION OF UNUSUAL EVENT

ALERT

SIYE AREA EMERGENCY

GENERAL EMERGENCY

- 1. MC system activity greater than Tech Spec limits in Modes 1-5.
- Greater than 1.0 microcurie per gram dose equivalent I-131 for greater than 48 hrs. continuous per chemistry analysis in modes 1-5.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.8.

 Dose equivalent I-131 in excess of Tech Spec Figure 3.4-1 per Chemistry analysis in modes 1-5.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.8.

 Specific activity greater than 100/E microcuries per gram per Chemistry analysis.

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.4.8

- 1. Severe loss of fuel cladding in Modes 1-5.
- Valid increase of 1000 times background setpoints of any containment radiation monitor in modes 1-5.
- Valid increase of 1000 times background setpoint of reactor coolant system process sonitor (EMP-48) in modes 1-5.
- * Chemistry analysis indicates greater than or equal to 5% total fuel clad failure or increase of 1% fuel failures within 30 sinutes in modes 1-5.

END

- Degraded core with possible loss of coolable geometry.
- e average of five highest core exit T/C's indicates greater than or equal to 700 Deg. F.
- Lower Range RVLIS less than 43% level during a LOCA event.
- RVLIS D/P setpoint at value which requires entry into Degraded Core Cooling section of Emergency Procedures.
- Containment hydrogen concentration greater than or equal to 1% and increasing greater than or equal to 0.1% per hour.
- containment EMF's (51s or 51b) valid reading of 179 R/hr.

 Loss of 2 of 3 fission product barriers with potential for loss of 3rd barrier.

more: To classify at this level, at least one condition from two of the three categories (A,B,C) must be satisfied and at least one condition from the third category must be satisfied or have the potential to be satisfied.

- A. Loss of clad barrier
- Total fuel clad failure greater than 5% per Chemistry analysis.
- * Containment EMF 51a or 51b valid reading of 117 R/hr (equates to 5% fuel gap activity released to containment)
- Plant conditions require entry into EP/1 or 2/A/5000/12.1 (Response to Inadequate Core Cooling).

BND

ENC

WOGUIRE NUCLEAR STATION EMERCENCY ACTION LEVELS EVENT # 4.1.2 FUEL DAMAGE

CMIP-11 ESCLOSURE 4.1

> GENERAL ENERGYSCY

PAGE 5 OF 29

BOTIFICATION OF UNUSUAL EVENT BLERT

SITE AREA DEERGEECY

- 9. Loss of Reactor Coolant System barrier
- Reactor Coolant System leak (including S/G tube leak) greater than 50 gpm.
- C. Loss of Containment Barrier
- * Incomplete containment integrity
- * Known containment leakage in access of Tech Specu.
- Containment pressure greater than or equal to 60 peig
- Containment atmosphere H² concentration greater than or equal to 9%
- Unisolable secondary (main steam or feedwater) break outside containment on the ruptured S/G with S/G tube leak greater than 50 gpm

MCGUIRE SUCLEAR STATION EMERGENCY ACTION LEVELS EVENT \$ 4.1.3 STEAM SYSTEM FAILURE

CMIP-11 ENCLOSURE 4.1 PAGE 6 OF 29

MOTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA ENERGENCY

MERAL CY

- Secondary (main steam or feedwater) line break which results in rapid depressurization of the secondary side.
- Secondary (main steam or feedwater) line break causing depressurization which results in safety injection or main steam isolation

RND

- Unisolable secondary (main steam or feedwater) line break outside containment with a S/G tube leak.
- Unisolable secondary (main steam or feedwater) line break outside containment.

ASID

NC subcooling greater than 0 Deg. F.

AND

S/G tube leak greater than 10 gpm, but less than 50 gpm on the faulted S/G

 Unisolable secondary (main steam or feedwater) line break outside containment.

AND

Field monitoring teams detect activity at the protected area fence at greater than or equal to 2 mRem/hr whole body.

- 1. Unisolable secondary (main steam or feedwater) break outside containment with a S/G tube loak.
- Unisolable secondary (main steam or feedwater) break outside containment.

AND

Primary to secondary leakage greater than 50 gpm on the faulted S/G.

- 2. Secondary (main stems or feedwater) break inside containment with S/S tube leak and indication of fuel damage
- Unisolable secondary (main steam or feedwater) break inside containment

AND

Primary to secondary leakage greater than 50 gpm on the faulted 5/G

AND

M/A

MCGIIRE MUCLEAR STATION EMEMGENCY ACTION LEVELS EVENT # 4.1.3 STRAM SYSTEM PAILIBLE

CMIP-11 ERCLOSURE 4.1 PAGE 7 OF 29

MOTIFICATION OF UNUSUAL EVENT ALERT

SITE AREA EMERGENCY

GENERAL EMERGENCY

- Secondary (main steam or feedwater) line break with failure of ECCS or Main Steam Isolation.
- Secondary (main steam or feedwater) line break depressurization which results in safety injection signal.

AND

Failure of both trains of ECCS injection.

 Secondary (main ateam or feedwater) line break depressurization which results in Main Steam Isolation signal.

AND

Pailure of two or more Main Steam Isolation Valves to close.

END

Puel clad failure greater than 5% per chemistry analysis (or valid reading on EMP-51a or 51b of 117 R/hr.

MCGUIRE MUCLEAR STATION EMERGENCY ACTION LEVELS EVENT # 4.1.4 SIGH RADIATION/RADIOLOGICAL EFFLUENTS

CMIP-11 ENCLOSURE 4.1 PAGE 8 OF 29

MOTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMERGENCY

GENERAL EMERGENCY

1. Liquid or gaseous radiological effluents exceed Tech Spec Limits as determined by RP or Chemistry Procedures.

END

- 1. Big. idiation levels or hi, airborne contamination
- Any valid area EMP reading greater than or equal to 1000 times background value

AND

Brcessive area radiation levels due to either unknown or uncontrolled causes

 Valid indication on EMF-41 reading greater than or equal to 1000 times background value

AND

Excessive airborne levels due to either unknown or uncontrolled causes

 Gaseous or liquid radiological effluents exceed 10 times Terh Spec limits.

- Accidental releases of gases
- Walid indication on EMF-36(L) reading greater than or equal to 7.25E6 cpm (equates to 50 mRem/hr WB at site boundary).
- Valid indication on EMF-36(B) reading greater than or equal to 6.1E2 cpm (equates to 50 mRem/hr WB at site boundary).
- Valid indication on EMF-37 reading greater than or equal to 2.8E5 cpm.
- Dose calculations based on containment conditions project dose rates at the site boundary greater than or equal to 50 mRem/hr WB or 250 mRem/hr thyroid

- Accidental releases of gases
- Valid indication on EMP-36(H) reading greater than or equal to 6.1E3 cpm (equates to 1 REM to the WB at site boundary integrated over 2 hours).
- Valid indication on EMF-37 reading greater than or equal to 2.8E6 cpm (equates to 5 Rem to the thyroid at site boundary integrated over 2 hours).
- Dose calculations based on containment conditions project dose rates at the site boundary greater than or equal to 1 R/hr wB or 5 R/hr thyroid integrated over a 2 hour period.
- * Field monitoring team measurements have determined dose rates at the site boundary greate. than or equal to 1 R/hr & or 5 R/hr thyroid integrated over a 3 hour period.

HECUIRE BUCLEAR STATION
EMERGENCY ACTION LEVELS
EVENT # 4.1.4 BIGH RADIATION/RADIOLOGICAL EFFLUENCE

CMIP-11 EMCLOSURE 4.1 PAGE 9 OF 29

MOTIFICATION OF UNUSUAL SVENT ALERT

SITE AREA EMERGENCY

CHERRAL EMERGRACY

- Valid indication on ENF-3 reading greater than or equal to 10 times Trip II setpoint
- Valid indication on RMF-36(L) reading greater than or equal to 10 times Trip II setpoint
- Valid indication on EMF-37 reading greater thun or equal to 19 times Trip II setpoint
- Valid indication on EMF-50 reading greater than or equal to 10 times Trip II setpoint
- Valid indication on EMP-31 reading greater than or equal to 10 times Trip 12 setpoint
- Valid indication on EMF-49 reading greater than or equal to 10 times Trip II setpoint
- Valid Indication on EMF-44 reading greater than or equal to 10 times Trip II setpoint

i monitoring team arements have actermined dose rates at the site boundary greater than or equal to 50 mRem/hr N3 or 250 mRem/hr thyroid.

MCGUIRE MICLEAR STATION EMERCENCY ACTION LEVELS EVENT \$ 4.1.4 HIGH RAD ATION/RADIOLOGICAL EFFLUENTS

patter, -

CMIP-11 ENCLOSINE 4.1 PAGE 10 OF 29

MOTIFICATION OF UNUSUAL EVENT ALERT

. SITE AREA EMERGERCY

GENERAL

• Gaseous or liquid radiological effluents exceed 10 time. Tech Spec limits as determined by RP or chemistry procedures

MCGUIRE MRCLEGE STATION EMERGENCY ACTION LEVELS EVENT # 4.1.5 LOSS OF SEUTDOWN FUNCTIONS

CMIP-11 RECLOSURE 4.1 PAGE 11 OF 29

MOTIFICATION OF UNUSUAL EVENT

ALERT

SIYE AREA EMERGERCY

CENERAL.

- 1. Loss of Decay Heat Removal in modes 5 and 6
- Loss of decay heat removal for greater than 10 minutes in modes 5 and 6

END

- Complete loss of any function needed to maintain core cooling in modes 5 and 6.
 - NOTE: If loss of RHR due to loss of vital AC or DC power, see Event #4.1.6, Loss of Power, Site Area Emergenc, Initiating Condition #3.
- Pailure of heat sink in m.des 5 and 6 results in uncontrolled heatup

AND

Core exit T/C's indicate greater than or equal to 200 Deg. F

2. Transient with failure of the Reactor Protection System to automatically initiate and complete a Rx trip which brings the Reactor Subcritical (ATWS Event)

- Complete loss of any function needed for hot shutdown conditions
- * Failure of heat eink in mode 4 results in uncontrolled heatup

ANT

Core exit T/C's indicate greater than or equal to 350 Deg. F.

 Inability to feed S/G's from any cource in Mode 1-3

DNG

Feed and blend cooling of the reactor core is necessary to remove core decay heat.

- Transient initiated by lose of CF and CM systems followed by failure of heat removal capability for an extended period.
- Loss of CM/CF feedwater flow capability.

AND

CA flow cannot be established within 30 minutes.

AND

MC system feed and bleed cannot be established or maintained.

- Transient requiring a Rx trip with failure to trip with indication of significant fuel damage or failure of core cooling.
- * Transient with failure of the reactor protection system to automatically initiate and complete a Rx trip which brings the reactor subcritical (ATWS event).

AND

MCGUIRE MUCLEAR STATION EMERGENCY ACTION LEVELS EVERT # 4.1.5 LOSS OF SHUTDOWN PUNCTIONS

CMIP-11 ENCLOSURE 4.1 PAGE 12 OF 29

WOTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMERGENCY

GENERAL EMERGENCY

- Degradation of Secondary Reat Sink
- Loss of feed capability to S/G's from main feed pumps.

AND

All S/G's levels less than 5% (25%) NR level

AND

Total CA flow to S/G's less than 450 gpm

- Complete loss of any function needed to achieve mode 5 when shutdown is required by Tech Spec in modes 1-4
- * Complete loss of any of the following functions when function is required to continue shutdown
 - (a) Ability to borate;
 (b) Ability to feed
 steam generators;
 (c) Ability to
 establish decay heat
 removal

- Transient requiring operation of sbutdown systems with failure to trip.
- Transient with failure of the reactor protection system to automatically initiate and complete a Rx trip which brings the reactor subcritical (ATWS event).

AND

Control rods cannot be manually tripped or Inserted from the Control Room Actions taken per EP/1 or 2/A/5300/11.1 (Response to Nuclear Power Generation/ATMS) fail to bring the reactor subcritical.

AMD

Chemistry analysis indicates greater than or equal to 5% total fuel clad failure (or valid reading on RMF-51a or 51b of 117 R/hr.

 Transiest with failure of reactor protection systems to automatically initiate and complete a Rx trip which brings the reactor subcritical

AND

Actions taken per EP/1 or 2/A/5000/11.1 (Response to Nuclear Power Generation/ATWS) feil to bring the reactor subcritical.

AND

Plant conditions require entry into EP/1 or 2/A/5000/12.1 (Response to Inadequate Core Cooling).

RVENT # 4.1.5 LCSS OF SHUTDOWN PURCTIONS MOGITIES MUNICAN STATICH EMERICANCY ACTION LEVELS

> MOTIFICATIC OF ORUSUAL EVERT

ALKET

PAGE 13 OF 29 RMCLOSURE 4.1 CMIP-II

EMERGERICT GENERAL.

SITE AREA EMERCEMEN

- Inability to maintain inventory in Modes 5 cold shutdown with loss of reactor wessel coolant end 6.
- shutdown conditions in · Pailure of heat sink causes loss of cold modes 5 and 6.

AMD

level decreating after Lower Range RVLIS Initiation of MC System Makeup.

shutdown conditions in · Pailure of heat sink causes loss of cold modes 5 and 6.

ANCD

NC system narrow range inches and decreasing after initiation of NC level less than 14 System Makeup.

- subsequent core uncovery in 3. Loss of heat sink with Hodes 5 and 6.
- conditions in modes 5 and 6. # Failure of heat sink causes loss of cold shutdown

AMD

substantially uncovered Lower Range RVLIS level indicates core remains (less than 43% level).

conditions in modes 5 and 6. * Failure of heat sink causes loss of cold shutdown

AMD

superheat at the core exit. Core Exit T/C's indicate

AMED

Instrumentation or rate of Available makeup rate (as FNST Level decrease) less than applicable data book indicated by Flow Rate CULTUR.

MCGUIRE WICLEAR STATION RHERGERCY ACTION LEVELS EVENT # 4.1.5 LOSS OF SHUTDOWN FUNCTIONS

CMIP-"1 ENCLOSURE 4.1 PAGE 14 OF 29

MOTIFICATION OF UNUSUAL EVENT ALERT

SITE AREA EMERCENCY

GENERAL EMERGENCY

 Pailure of heat sink causes loss of Cold Shutdown conditions in modes 5 and 6.

AND

Bither Train ultrasonic level indication less than 14 inches and decreasing after initiation of MC system makeup.

 Failure of heat sink causes lose of cold shutdown conditions in modes 5 and 6.

AND

Reliable NC System level indication unavailable due to NC system pressurization.

AND

Core exit T/C's or AP/1 or 2/A/5500/19 (Loss of Residual Heat Removal) data indicate boiling in the core.

AND

Failure of heat sink causes loss of cold shutdown conditions in modes 5 and 5.

AND

Available makeup rate (as indicated by Flow Rate Instrumentation or rate of FWST Level decrease) less than applicable data book curve.

AND

NC System level below bottom range of available level indication.

AND

Emergency Coordinator judgement that core uncovery is imminent.

MCGUIRE EUCLEAR STATION ENGRIPHCY ACTION LEVELS EVENT # 4.1.5 LOSS OF SECTIONS FUNCTIONS

CMIP-11 ENCLOSINE 4.1 PAGE 15 OF 29

NOTIFICATION OF UNUSUAL EVENT ALKRT

SITE AREA EMERGENCY

GENERAL.

Available makeup rate (as indicated by flow rate instrumentation or rate of FWST level decrease) less than applicable data book curve.

MCGUIRE MUCLEAR STATION EMERGENCY ACTION LEVELS EVERT # 4.1.6 LOSS OF POWER

CMIP-11 PMCLOSURE 4.1 PAGE 16 OF 29

MOTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMERGENCY

GENERAL EMERGENCY

- Loss of offsite power in Modes 1-6.
- Both unit related main bus lines de-energized in modes 1-6.
- Loss of onsite MC power capability in Modes 1-4.
- Both D/G's are incapable (for greater than 2 hours) of powering the 4160 V essential buses in modes 1-4.
- Loes of onsite AC power capability in Modes 5 and 6.
- Both D/G's are incapable (for greater than 8 hours) of powering the 4160 V essential buses in modes 5 and 6.

- Loss of offsite power and loss of all onsite AC power for greater than 1 simute in Modes 1-4.
- Both 4160 V essential buses are de-energized for greater than 1 minute but less than or equal to 15 minutes in modes 1-4
- Loss of all wital DC power for up to 15 minutes in Modes 1-4.
- Both unit related BVDA and EVDD buses deenergized for up to 15 minutes in modes 1-4
- Lose of offsite power and loss of all onsite AC power for greater than 15 minutes in Modes 5 and 6.
- Both 4160 V essential buses are de-energized for greater than 15 minutes in modes 5 and 6.

- Loss of offsite power and loss of all onsite AC power for greater than 15 minutes in Modes 1-4.
- Both 4160 V essential buses are de-energized for greater than 15 minutes in Modes 1-4.
- Lose of all vital DC power for greater than 15 minutes in Bodes 1-4.
- Both unit related EVDA and EVDD buses deenergized for greater than 15 minutes in Modes 1-4.
- Lose of all oneite AC or DC power for greater than 15 minutes with uncontrolled reactor core heatup in Modes 5 and 6.
-) Both 4160 V essential buses are de-energized for greater than 15 minutes in modes 5 and 6

- Loss of offsite power and loss of all onsite AC power with total loss of S/G's feed capability in Nodes 1-4.
- Both 4'. V essential buses are de-boergized in modes 1-4.

AND

Loss of CM/CF feedwater flow capability.

AND

CA flow cannot be established within 30 minutes.

MCGUIRE MUCLEAR STATION EMERGENCY ACTION LEVELS EVENT # 4.1.6 LOSS OF POMER

CMIP-11 ENCLOSURE 4.1 PAGE 17 OF 29

MOTIFICATION OF UNUSUAL EVENT ALERT

SITE AREA EMERGENCY

GENERAL EMERGENCY

- Loss of all onsite AC or BC power greater than 1 minute but less than 15 minutes in modes 5 and 6.
- Both 4160 V essential buses are de energized for greater than 1 minute but less than 15 minutes in modes 5 and 6
- Both unit related EVDA and EVDD buses de-energized for greater than 1 minute but less than 15 minutes in modes 5 and 6

RND

- Loss of all vital DC power for greater than 15 minutes in Modes 5 and 6.
- 6 Both unit related EVDA and EVDD buses deenergized for greater than 15 minutes in modes 5 and 6.

END

Valid core exit temperature of greater than 200 Deg. F

* Both unit related EVDA and EVDD buses deenergized for greater than 15 minutes in modes 5 and 6

AFD

Valid core exit temperature of greater than 200 Deg. F.

MCGUIRE BUCLEAR STATION EMERGENCY ACTION LEVELS EVENT # 4.1.7 FIRES AND SECURITY ACTIONS

CMIP-11 EMCLOSURE 4.1 PAGE 18 OF 29

MOTIFICATION OF UNUSUAL EVERT

ALERT

SITE AREA EMERGERACY

GENERAL. EMERGENCY

- Fire (as determined by the Shift Supervisor or designee) within the plant (see NOTE) lasting longer than 10 minutes.
- 2. Security threat.
- Discovery of bomb within the site boundary but outside the protected area.
- · Civil disturbance (hostile)
- Intrusion/Attempted Intrusion (Protected Area)
- * Hostage situation/extortion
- Security threat as determined by Emergency Coordinator and Security

END

NOTE: Plant is defined as: Aux. Bldg, TB, SB, RB, D/G Rm, Doghouses, SSP, Interim Radwaste Facility.

- Fires potentially affecting safety systems.
- Fire resulting in potential deterioration (visible or assumed) to any ESF component (see Encl. 4.2) or ESF component subsystem required by Tech Specs for the current operating mode.
- Ongoing Security compromise.
- Adversaries commandeer an area of the plant but do not control any plant vital areas.
- Discovery of breached barrier caused by intrusion or sabotage in Vital Area
- Discovery of bomb in the protected area

- Fire compromising the function of safety systems.
- * Fire resulting in red. ant trains of ESF components (see Encl. 4.2) or ESF components subsystems required by Tech Specs for the current operating mode becoming incapable of performing their design function (inoperable)
- * Fire requiring Control Room evacuation

AMD

Control of shutdown systems has been established or is in the process of being established from the SSF.

Isminent loss of physical control of a plant vital area.

- Any major fire which could cause massive common damagn to plant systems.
- Fire requiring Control Room evacuation

AND

Control of Shutdown systems cannot be established from any plant location

AMD

NC subcooling cannot be maintained greater than D Deg. F.

- Security threat resulting in loss of physical control of the plant.
- Physical attack on the plant (see Note) has resulted in occupancy of the control room or other vital areas.

MCGUIRE NUCLEAR STATION RECORGENCY ACTION LEVELS EVENT # 4.1.7 FIRES AND SECURITY ACTIONS

CMIP-11 PMCLOSURE 4.1 PME 19 OF 29

MUTIFICATION OF UNUSUAL EVENT

ALBRT

SITE AREA EMERGERCY

GREERAL EMERGENCY

- * Ongoing security compromise as determined by Emergency Coordinator and Security
 - END

- Physical attack resulting in imminent occupancy of the Control Room or other vital areas.
- Discovery of bomb in a plant Vital Area.

MCGUIRE BUKIRAR STATION EMERGENCY ACTION LEVELS EVENT # 4.1.6 SPENT FUEL DAMAGE

CMIP-11 EMCLASSINE 4.1 PAGE 20 OF 29

MUTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMMRGENCY

GENERAL.

N/A

 Damage to Spent Fuel with release of radioactivity. Major damage to spent fuel with release of radioactivity. N/A

CONTAINMENT

 Valid Trip II Alarm on 1EMF-39

AND

Report of fuel damage due to loads dropped into core or during core alterations or movement of spent fuel in Containment

 Valid Trip II alarm on 2EMF-39

AND

Report of fur. damage due to loads dropped into core or during core alterations or movement of spent fuel in containment.

CONTAINMENT

 Valid Trip II Alarm on 1EMF-16 (for Unit 1) or 2EMF-3 (for Unit 2)

AND

Valid 1(2)EMF-79 off scale high

AND

Report of fuel damage due to loade dropped into core or during core alterations or movement of spent fuel in Containment

AND

Dose rate inside Containment coupled with known Containment leak rate results in calculated dose rate at the Site Boundary of greater than or equal to 50 arem/hr WB or 250 arem/hr thyroid.

McGUIRE MECLEAR STATION EMERGENCY ACTION LEVELS EVENT \$ 4.1.8 SPENT FUEL DAMAGE

CMIP-11 ENCLOSURE 4.1 PAGE 21 OF 29

WOTIFICATION OF UNUSUAL EVENT ALERT

SITE AREA EMERCENCY

GENERAL EMERGENCY

FUEL HANDLING BUILDING

 Valid Trip II Alarm on 1EMF-17 (or equivalenc)

AND

Valid Trip II Alarm on 1EMF-42

AND

Report of fuel damage during movement of spent fuel or loads dropped into spent fuel pool resulting in possible fuel damage.

 Valid Trip II Alarm on 2EMF-4 (or equivalent)

AND

Valid Trip II Alarm on 2EMP-42

AND

Report of fuel damage during movement of spent fuel or loads dropped into spent fuel pool resulting in possible fuel damage. FURL HANDLING BUILDING

 Valid Trip II Alarm on 1EMF-17 (or equivalent)

AND

Valid Trip II Alarm on 1EMF-42

AND

Valid indication on 1EMF-36 reading greater than or equal to 3.2526 cpm.

AND

Report of fuel damage during movement of spent fuel or loads dropped into spent fuel pool resulting in possible fuel damage.

• Valid Trip II Alarm on 2EMF-4

AND

Valid Trip II Alarm on 2EMF-42

AND

INCUIRE MUCLEAR STATION RHENGERCY ACTION LEVELS EVENT # 4.1.8 SPERT FUEL DAMAGE

CMIP-11 EMCLOSURF 4.1 PAGE 22 # 29

MOTIFICATION OF UNUSUAL EVENT ALEPT

SITE AREA RHENGENCY

GEMERAL.

Valid indication on 2ENF-36 reading greater than or equal to 3.25E6 cpm

AND

Report of fuel damage during movement of spent fuel or loads dropped into spent fuel pool resulting in possible fuel damage.

MCGUIRE MUCLEAR STATION EMERGENCY ACTION LEVELS EVERT # 4.1.9 NATURAL DISASTERS AND OTHER SALARDS

CMIP-11 ENCLOSURE 4.1 PAGE 23 OF 29

MOTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMERGENCY

GENERAL EMERGENCY

- Rarthquaks felt in plant and detected by seissic monitoring instruments
- Valid Alarm on "strong motion accelerograph"
- Valid Alaxm on "Peak shock annunciator"
- 2. Low water level
- Lake Norman level less than or equal to 745 ft.
- Asy tornado/severe weather within the site boundary.
- Any tornado observed touching down within the site boundary
- Sustained (greater than 15 minutes) winds greater than or equal to 60 mph
- 4. Aircraft crash
- Aircraft crash within the site boundary.

- 1. Eurthquake greater than ORE
- * Greater than 0.08 g Horizontal
- * Greater than 0.053 g Vertical
- Damage from tornado, sustained wieds, aircraft crash, missile, or explosion.
- Any tornado striking plant structures within the protected area fence
- Approaching hurricane with sustained (greater than 15 minutes) winds greater than 75 but less than 95 mph as reported by the National Weather Servi
- Aircraft crash within the protected area fence affecting safe operation of the unit.

- Earthquake greater than SSR in modes 1-4.
- # Greater than 0.15 g Horizontal
- Greater than 0.10 g
 Vertical
- Damage from torrado, sustained winds, aircraft crash. missile, or explosion.
- Any tornado striking any plant vital area structure resulting in loss of any ESF function required for the current operating mode.
- Approaching hurricane with sustained (greater than 15 minutes) winds greater than 95 mph as reported by the National Weather Service.

- Any major natural or accidental event(s) (ie: aircraft impact, earthquakes substantially beyond design levels) which could cause massive common damage to plant systems.
- * Emergency Cooldinator judgement.

REQUIRE NUCLEAR STATION EXERGENCY ACTION LEVELS EVENT # 4.1.9 NATURAL DISASTERS AND OTHER HARANDS

CMIP-11 ENCLOSURE 4.1 PAGE 24 OF 29

MOTIFICATION OF UNESUAL EVENT

ALERT

SITE AREA ENERGENCY

GENERAL EMERGENCY

- 5. Train derailment on alte
- Train derailment resulting in physical damage to equipment/structure within site boundary.
- Explosion within site boundary.
- Explosion within the site boundary resulting in structural damage to buildings and/or injuries to personnel.
- Release of toxic or flammable gases.
- Release of toxic gas resulting in personnel injury or any evacuation within the Protected Area.
- Release of flammable gas resulting in any evacuation within the Protected Area.

END

- Explosion damage within the protected area fence affecting safe operation of the unit.
- Release of toxic or flammable gas.
- Uncontrolled entry of toxic or flammable gas within protected area fence affecting safe operation of the unit.

END

- Aircraft crash causing damage or fire to the Containment Building, Control Room, Auxiliary Building, Fuel Building, or SNSWP Intake Structure in modes 1-4.
- Damage from missile or explosion in modec 1-4 causes inability to maintain or establish functions required for hot shutdown.
- Release of toxic or flasmable gas (Modes 1-4).
- * Uncontrolled entry of toxic or flammable gases into the Control Room, Cable Spreading Rooms, Contrinment Building, Switchgear Roome, Auxiliary Shutdown panels area (CA pump rooms), or Emergency Diesel Generator Rooms affecting safe operation of the unit in modes 1-4.

CMB

MOGUIRE MUCLEAR STATION EMERGENC1 ACTION LEVELS EVENT \$ 4.1.10 OTHER ARMORMAL PLACT COMDITIONS

CMIP-11 RWCLOSURE 4.1 PAGE 25 OF 29

MUTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMERGENCY

GENERAL ENGRICERCY

- 1. BCCS initiated.
- Valid S/I signal rerified by redundant indication

AND)

Discharge into the vessel.

- Abnormal coclast temperature and/or pressure or abnormal fuel temperature.
- Figure 2.1-1 Tech Spec exceeded in modes 1 and 2
- Core sub-cooling margin less than acceptable ("Subcooling Margin Alert" annunciator).
- Tech Spec (LCO 2.1.2)
 Reactor Coolant system
 pressure exceeded in modes
 3, 4, and 5.
- Loss of containment integrity requiring shutdown by Tech Spec.
- Any automatic containment isolation valve open and inoperable and unisolable.

- 1. Evacuation of Control Room.
- * Evacuation of Control Room

AND

Control established (or in process of being established) from the Auxiliary Shutdown Panel less than or equal to 15 minutes.

- Significant loss of annunciator capability in Modes 1-4.
- Loss of 50% or more of the control room annunciators for greater than 15 minutes in Modes 1-4.
- Other unit conditions exist that in the judgement of the Shift Supervisor /Reergency Coordinator warrant declaration of the Alert classification.

ENT:

- 1. Evacuation of Control Room.
- * Evacuation of Control Room in modes 1-3

AND

Inability to feed S/G's from any source

8 Evacuation of Control Room in Modes 1-3.

AND

Inability to establish control from Auxiliary Shutdown panel within 15 minutes.

 Evacuation of Control Room

AND

Inability to establish control from Auxiliary Shutdown parel

AND

Control established (or in process of being established) from SSF.

- 1. Evacuation of Control Room.
- * Evacuation of Control Room

AND

Control cannot be established from any plant location

AND

NC Subcooling cannot be maintained greater than 0 Dec. P.

 Other unit conditions exist, from whatever source, that in the judgement of the Shift Supervisor/Reergency Coordinator make release of large amounts of radioactivity in a short time period possible.

MCGUIRE MALEAR STATION EMERGRACY ACTION LEVELS EVENT \$ 4.1.10 OTHER ARMODIAL PLANT COMDITIONS

CMIP-11

PROLOGUES 4.1 PROE 26 OF 29

MOTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMERCENCY

GENERAL ENERGENCY

AND

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.6.3.

 Both air lock Goors of a single airlock inoperable

AMI)

Load reduction or plant cooldown initiated pursuant to Tech Spec 3.6.1.3.

- 4. Loss of ESF or Pire Protection System function.
- Both trains of any ESF function found inoperable (if caused by fire see event
 4.1.7 - Fires and Security Actions, Site Area Emergency Classification).

AND

Load reduction or plant cooldown initiated in accordance with Tech Space.

 Other unit conditions exist that in the judgement of the Shift Supervisor /Emergency Coordinator warrant declaration of Jite Area Emergency.

MCGBIRE NUCLEAR STATION EMERGENCY ACTION LEVELS EVENT # 4.1.10 OTHER ABBORNAL PLANT CONDITIONS

CMIP-11

PAGE 27 OF 29

SOTIFICATION OF UNUSUAL EVENT ALERT

SITE AREA ENERGENCY

GENERAL EMERGENCY

 Less than minimum channels of ESF function operable.

AND

Load reduction or plant cooldown initiated in accordance with Tech Specs.

- Loss of all main fire protection system water pumps.
- Transportation of a contaminated injured individual from the site to an offsite medical facility.
- Decontamination efforts fail to reduce external contamination below 150 cpm bets-gamma or injured may require immediate medical attention and decontamination efforts are waived.

CMA

Radiation Protection personnel determine that radiological controls are required for offsite medical treatment.

MCGUIRE MUCLEAR STATION RMENGENCY ACTION LEVELS EVERT # 4.1.10 OTHER ARMONNAL PLANT COMDITIONS

CMIP-11 ENCLOSURE 4.1 PAGE 28 OF 29

MOTIFICATION OF UNUSUAL EVENT ALERT

SITE AREA EMBRICENCY

GENERAL EMERCENCY

- Internal contamination requiring medical assessment/treatment
- External exposure requiring medical assessment/treatment
- Significant Loss of assessment capability or communication capability.
- Loss of MNS communications capability with all offsite agencies
- Loss of 50% or more of the control room annunciators in Modes 5, 6 for greater than 15 minutes
- Loss of all onsite meteorological instrumentation

AND

Inability to contact the National Weather Service for backup source of data.

MCGUIRE MURILRAR STAFFOR
EMENGENCY ACTION LEVELS
EVENT # 4.1.10 OTHER ASHORMAL PLANT CONDITIONS

CMIP-11 ENCLOSURE 4.1 PAGE 29 OF 29

MUTIFICATION OF UNUSUAL EVENT

ALERT

SITE AREA EMERGENCY

GENERAL EMERGENCY

 Other conditions exist that in the judgement of Shift Supervisor/Leergency Coordinator warrant increased awareness of local authorities.

ENGINEERED SAFETY FEATURES

- 1) Containment Spray
- 2) Containment Air Return and Hydrogen Skimmer
- 3) Ice Condenser
- 4) Hydrogen Control (Hydrogen Recombiners Only)
- 5) Annulus Venti ation
- 6) Auxiliary Feedwater
- 7) Nuclear Service Water
- 8) Component Cooling
- 9) Steam Line/Feedwater Line Isolation
- 10) Containment Pressure Control
- 11) ESF Interlocks
- 12) Turbine Trip
- 13) Reactor Protection System
- 14) Emergency Diesel Generators
- 15) Emergency Switchgear
- 16) Loss of Power Actuation Circuit
- 17) Emergency Core Cooling System Safety Injection, Residual Heat Removal, Cold Leg Accumulators, Upper Head Injection, Chemical and Volume Control System, Automatic Switchover
- 18) Containment Isolation Phase "A" and Phase "8"

TERMINATION CRITERIA

	1.	Existing conditions no longer meet the emergency classification criteria and it appears unlikely that conditions will deteriorate further.
	2.	No surveillance relative to off-site protective actions is needed, except for the control of foodstuffs and water, and off-site contamination, or environmental assessment activities.
	3.	Radiation levels in affected in-plant areas are stable or decreasing to below acceptable levels.
	4.	Releases of radioactive material to the environment greater than Technical Specifications are under control or have ceased.
	5.	The potential for gan uncontrolled release of radioactive material is at an acceptably low level.
	6.	Containment pressure is within Technical Specification requirements.
A MANAGEMENT TOW	7.	Adequate long-term core cooling is available.
***	8.	Adequate shutdown margin of the core has been verified.
	9.	A fire, flood, earthquake or similar emergency condition is controlled or has ceased.
Alexander considerate	10.	Offsite power is available per Technical Specifications.
COMMUNICATION OF CA	11.	Any contaminated/injured personnel have been transported offsite and are receiving appropriate medical care.
	12.	All emergency action level notifications have been completed.
	13.	Access to radiologically controlled areas of the plant necessary for operation during recovery are being monitored by the Radiation Protection Section.
	14.	Offsite conditions will not limit access of personnel and support resources.
	15.	Discussions have been held with the News Director to determine the impact of termination on public in. mation management.
	16.	Discussions have been held with Senior NRC and State representatives to determine the impact of termination on their activities.