



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

JUL 10 1984

MEMORANDUM FOR: Dr. John H. Hopps  
Manager, Energy Program Development  
The Charles Stark Draper Laboratories

FROM: Dorothy J. Zukor  
Reactor Systems 2  
Reactor Operations Analysis Branch

SUBJECT: DATA ON NUCLEAR PLANT TRANSIENTS

In response to our recent telephone discussion, I am sending you another copy of the information which was previously sent to you. The reports for the following events are included:

1. Ginna Steam Generator Tube Rupture on January 25, 1982.
  - o NUREG 0909
2. Salem Unit 2 Load Transient on January 14, 1982.
  - o Engineering Evaluation by N. Trehan
  - o Supplemental Reportable Occurrence on LER 82-04/03X-1.
3. Brunswick Unit 2 Loss of Residual Heat Removal Service Water on January 16, 1982.
  - o Engineering Evaluation by T. Wolf.
  - o LER 82-005/0T-1

I hope you find the enclosed information useful. If you should need any further assistance, please feel free to contact me at (301) 492-4431.

Dorothy J. Zukor  
Reactor Systems 2  
Reactor Operations Analysis Branch

Enclosure:

1. NUREG 0909 - Ginna SGTR
2. Engineering Evaluation "Salem Unit 2 Load Transient" with LER 82-04/03X-1
3. Engineering Evaluation "Brunswick Unit 2 Loss of RHR Service Water"

8407180021

L144