




LOUISIANA

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

October 13, 1983

W3K83-1553
Q-3-A35.07.77

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L Letter W3I83-0255 dated July 29, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 77
"Inadequate Containment Purge Valves Closure Time and Flow Rate"
Fifth Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC on October 14, 1983.

At the present time, a continuing effort is being made to review supporting documentation. Completion of this review is expected by November 28, 1983.

A Final Report will be submitted to the USNRC on December 15, 1983.

Very truly yours,

T. F. Gerrets
T. F. Gerrets
Quality Assurance Manager

TFG:CNH:SSTG

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8310280069 831013
PDR ADOCK 05000382
S PDR

110
IE-27

Mr. John T. Collins
October 13, 1983
W3K83- 1553
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130