Arizona Public Service Company May 14, 1984 ANPP-29494-TDS/TRB U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368 Attention: Mr. T. W. Bishop, Director Division of Resident Reactor Projects and Engineering Programs Time Extension For Report - DER 83-78 Subject: A 50.55(e) Potentially Reportable Deficiency Relating To No Documentation Of Users Test And No Controlling Procedure For Rock Bolt Expansion Anchors. File: 84-019-026; D.4.33.2 Reference: (A) Telephone conversation between P. Narbut and K. Parrish on November 9, 1983. (B) ANPP-28393, dated December 8, 1983 (Interim Report) (C) ANPP-28801, dated February 6, 1984 (Time Extension) Dear Sir: The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by May 16, 1984. Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by June 15, 1984, at which time a complete report will be submitted. There is no new information or change to the Interim Report at this time. Very truly yours, E. E. Van Brunt, Jr. APS Vice President, Nuclear ANPP Project Director EEVB/TRB:db cc: See Page Two 8405240253 8405 1E-271 PDR ADOCK 05000528

Mr. T. W. Bishop DER 83-78 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

B. S. Kaplan

L. A. Souza

D. E. Fowler

J. Vorees

J. R. Bynum

J. M. Allen

P. P. Klute

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

G. A. Fiorelli

S. R. Frost

J. Self

D. Canady

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339