

SAFEGUARDS INFORMATION UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30323

Report Nos.: 50-250/92-05 and 50-251/92-05

Licensee: Florida Power and Light Company 9250 West Flagler Street Miami, FL 33102

Docket Nos.: 50-250 and 50-251

License Nos.: DPR-31 and DPR-41

Facility Name: Turkey Point 3 and 4

Inspection Conducted: February 18-21, 1992

R. McGutre, Chief

Accompanying Personnel: A. Tillman, Safeguards Inspector

Inspector: David Inspector D. Thompson, Safeguards Inspector

3-16-92 Date Signe1

3/16/92

Approved by: 1

Safeguards Section Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

SUMMARY

Scope:

10

6

This routine, unannounced inspection was conducted in the areas of Physical Security Program for Power Reactors, including; Security Program Plans and Audit; Protected and Vital Area Physical Barriers; Detection and Assessment Aids; Compensatory Measures, Security Communication and Safeguard Contingency Plans.

Results:	920326010 PDR ADOC	6 920318 K 05000250 PDR
	24	1. 6713

In the areas inspected, violations or deviations were not identified. Review and observation of security activities, during this inspection, confirmed that the management of the operational activities continued to be maintained at a satisfactory level. Security personnel continued to demonstrate a high level of job knowledge and professionalism in the performance of their duties. Continued efforts to improve security program efficiency and effectiveness were evidenced by the newly installed "video capture" feature which had enhanced the overall assessment capability and the conduct of an extensive contingency drill on February 20, 1992.

The inspectors reviewed, and found acceptable, the licensees action to reposition the end of line resistors from the junction boxes to the microwave detection units (Inspector Follow-up Item 91-44-01 Closed). It was concluded that the security organization was capable of providing an acceptable level of protection for the facility.

SAFEGUARDS INFORMATION