ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company McGuire Units 1 and 2

> 8405300162 840504 PDR ADDCK 05000369

PDR

Docket Nos. 50-369 and 50-370 License Nos. NPF-9 and NPF-17

The following violations were identified during an inspection conducted on December 20, 1983 - January 20, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

 Technical Specification 6.8.1.a requires that written procedures be implemented concerning control of safety-related equipment. Pre-requisite 4.6 of procedure IP-0-A-3010-06, an approved station procedure for surveillance testing of the Reactor Protection System (RPS) requires administrative control of affected equipment by placement of red tags.

Contrary to the above, operations personnel failed to place red tags on breakers of the decay heat removal system valves, ND-1 and ND-2. Subsequently, during the performance of the RPS test on January 15, 1984 and without the benefit of an administrative hold (red tags), power was erroneously restored to these subject valves which resulted in the loss of decay heat removal.

This is a Severity Level IV Violation (Supplement I). This is applicable to Unit 2 only.

 Technical Specification 6.8.1.d requires that written procedures be implemented covering emergency plan activities. Procedure PT-0-A-4600-11 is used for inventory of emergency protective equipment kits on a monthly basis.

Contrary to the above, the licensee discovered on January 3, 1984, that a technician failed to fully perform all sections of procedure PT-O-A-4600-11 and falsified its record resulting in degraded emergency equipment (batteries) when they were last detected in that condition on November 2, 1983.

This is a Severity Level IV Violation (Supplement I). This is applicable to Units 1 and 2.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Duke Power Company Notice of Violation

Docket Nos. 50-369 and 50-370 License Nos. NPF-9 and NPF-17

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

2

		· n	0	0	1084
Date:	+ 1	20	6	3	1984