Docket Nos. 50-317 50-318

Baltimore Gas and Electric Company
Calvert Cliffs Nuclear Power Plant
ATTN: Mr. George C. Creel
Vice President, Nuclear Energy
MD Rts 2 and 4, Post Office Box 1535
Lusby, Maryland 20657

Dear Mr. Creel:

SUBJECT: NOTICE OF VIOLATION

COMBINED INSPECTION REPORT NOS. 50-317/92-04 AND 50-318/92-04

This refers to the combined safety inspection conducted by Mr. F. L. Bower of this office from January 27 - 31, 1992, at Calvert Cliffs Nuclear Power Station, Lusby, Maryland, of activities authorized by NRC License Nos. DPR-53 and DPR-69 and to the discussions of our findings held by Mr. F. L. Bower of this office and Mr. G. Detter of your staff at the conclusion of the inspection.

Areas important to the health and safety of the public which were examined during this inspection are described in the NRC Region I Inspection Report enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, certain activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). We are concerned about the violations because of potential concerns which could result from a failure to follow procedures in accordance with established station requirements, and the possibility that some established requirements were not adequately defined, understood, or implemented by plant personnel. Although Section 2.201 requires you to submit to this office, within 20 days of your receipt of this Notice, a written statement of explanation, we note hat actions had been initiated to correct this violation and those proposed actions were reviewed during this inspection. Implementation of unexplorer corrective actions will be accomplished during a future inspection. Therefore, no response with respect to this matter is required.

OFFICIAL RECORD COPY A:CC9204 K:CC9204

EOI 1

Our inspection also noted one non-cited violation. This violation concerned a failure to provide a prompt corrective action to an audit finding. This violation will not be subject to enforcement, since the violation was considered isolated and you initiated prompt corrective actions. The NRC is exercising enforcement discretion since the criteria specified in the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy), Section V.A, was satisfied.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Lee H. Bettenhausen, Chief

Operations Branch

Division of Reactor Safety

Enclosure: Combined NRC Region Inspection Report Nos.

50-317/92-04 and 50-318/92-04

cc w/encl:

G. Detter, Director, Nuclear Regulatory Matters (CCNPP)

R. McLean, Administrator, Nuclear Evaluations

J. Walter, Engineering Division, Public Service Commission of Maryland

K. Burger, Esquire, Maryland People's Counsel

R. Ochs, Maryland Safe Energy Coalition

K. Abraham, PAO (2)

Public Document Room (PDR)

Local Public Document Room (LPDR)

Nuclear Safety Information Center (NSIC)

NRC Resident Inspector

State of Maryland (2)

bcc w/encl:

Region I Docket Room (with concurrences)

Management Assistant, DRMA (w/o encl)

W. Lanning, DRS

L. Bettenhausen, DRS

J. Joyner, DRSS

C. Cowgill, DRP

J. Yerokun, DRP

L. Nicholson, DRP

S. Greenlee, DRP

R. Lobel, EDO

R. Capra, NRR

D. McDonald, NRR

P. Madden, NRR

N. Blumberg, DRS

F. Bower, DRS

DRS SALP Coordinator

DRSS SALP Coordinator

DRS Files (5)

RI:DRS

Bower/dmg

RI:DRS

Blumberg

03/16/92

03/6/92

RI:DRS

Be Jonhausen

03//6/92

OFFICIAL RECORD COPY

A:CC9204 K:CC9204