

DmB



STONE & WEBSTER MICHIGAN, INC.

P. O. Box 1963, MIDLAND, MI 48641-1963

Mr. D. L. Quamme
Consumers Power Company
Midland Nuclear Plant
3500 East Miller Road
Midland, MI 48640

PRINCIPAL STAFF		
<input checked="" type="checkbox"/>	PRP	0/19 + 3
<input checked="" type="checkbox"/>	DE	
<input type="checkbox"/>	DRMSP	
<input type="checkbox"/>	DRMA	
<input type="checkbox"/>	SCS	
<input type="checkbox"/>	NL	
<input type="checkbox"/>	File	

May 17, 1984

J.O. No. 14509
SWM-116

Docket No. 50-329/330
Documentation Request for Module 120D
Construction Implementation Overview
Midland Nuclear Power Plant

Please provide the necessary documentation for the listed items to Stone & Webster Michigan, Inc. Construction Implementation Overview (CIO).

Drawing Numbers

- | | |
|-------------------|--------------------------|
| 2634-05-019RH010R | C-202 |
| 2634-05-020H011 | C-211 |
| 2634-05-11BH009 | C-218 |
| 2634-04-001H001 | C-219 |
| 2634-04-002H002 | C-220 |
| 2634-04-500H500 | C-221 |
| 2HBC055-01H002 | C-223 |
| 2HBC056-01H002 | C-224 |
| 2HBC183-04H001 | C-224/7 |
| 2HBC183-04H002 | C-233 |
| 2HBC184-04H001 | C-244 |
| 2HBC552-01H001 | C-283 |
| 2HBC552-01H002 | C-855 |
| 2HBC552-01H003 | C-862 |
| 2HBC552-01H004 | C-2052 |
| 2HBC698-01H001 | C-2053 |
| 2HBC648-01H002 | FSK CA-624 Sht 1 |
| A-72 | FSK CA-624 Sht 2 |
| C-36A-10-4 | FSK CA-661 |
| C-36A-9(21)-5 | FSK CA-663 |
| C-36A-9(20)-4 | FSK C-113 |
| C-140 | SK C-1034 |
| C-141 | VP-1.90-FSK-M-2HBC-183-4 |
| C-142 | VP-1.90-FSK-M-2HBC-56-1 |
| C-143 | VP-1.90-FSK-DV IM634-5 |
| C-147 | VP-1.90-M-634-4 |
| C-148 | VP-1.90-FSK-M-2HBC-552-1 |
| C-149 | VP-1.90-FSK-M-2HBC-184-4 |
| C-192-8 | VP-1.90-FSK-M-2HBC-55-1 |
| C-195 | |

B405300296 B40517
PDR ADOCK 05000329
S PDR


JE01 /10

MAY 24 1984

NCR Numbers

C-5157	C02574 M	C03119 M
C-3060	C02581 M	C03153 E
C-2934	C02706 I	C03154 E
C-1201	C02718 M	C03156 E
C-3011	C02767 M	C03163 I
C-1135	C02808 E	C03194 E
4062 E	C02809 E	C03198 E
4237 M	C02820 E	C03234 E
4778	C02834 C	C03238 E
5063 M	C02838 I	C03239 M
5167 M	C02869 E	C03250 E
6262 M	C02871 E	C03312 E
C00082 M	C02876 C	C03313 E
C01280 E	C02891 M	C03315 E
C01381 C	C02892 M	C03317 E
C01497 E	C02904 M	C03411 M
C01498 E	C02921 E	C03413 E
C01538 I	C02922 E	C03414 M
C01539 I	C02923 E	C03442 E
C01551 E	C02929 M	C03460 E
C01552 E	C02936 C	C03461 M
C01657 E	C02937 E	C03463 M
C01672 I	C02938 E	C03464 E
C01673 I	C02939 E	C03466 E
C01707 E	C02943 C	C03471 M
C01776 E	C02968 E	C03506 E
C01781 E	C02985 C	C03507 E
C01826 E	C02995 I	C03511 E
C01928 E	C03003 C	C03540 E
C01962 E	C03006 E	C03541 E
C02094 E	C03008 E	C03542 E
C02095 E	C03010 E	C03543 E
C02096 E	C03017 M	C03545 E
C02207 E	C03026 E	C03587 C
C02210 E	C03045 E	C03595 C
C02240 M	C03046 E	C03649 E
C02336 M	C03074 E	C03654 E
C02342 C	C03078 E	C03700 E
C02419 E	C03079 E	C03732 C
C02422 E	C03082 M	C03736 C
C02472 E	C03117 E	
C02554 M	C03118 E	

The documentation is required to support CIO evaluation of Module 120D.



J. E. Karr
CIO Program Manager

RSS:NL

cc:

NIRichel, CCo Midland (site)
RAWells, CCo Midland (site)
JGKepler, US NRC Glen Ellyn, IL
JJHarrison, US NRC Glen Ellyn, IL
BLBurgess, US NRC Midland (site)