

ENCLOSURE 1

NOTICE OF VIOLATION

Virginia Electric and Power Company
Surry Unit 1

Docket No. 50-280
License No. DPR-32

The following violations were identified during an inspection conducted on January 3-31, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 3.11.B.4 requires that gross and particulate activity and flow rate be continuously monitored and recorded during the release of radioactive gaseous wastes to the process vent.

Contrary to the above requirements, the contents of the A waste gas decay tank were released to the process vent from 3:15 p.m. on January 10, 1984, until 9:22 a.m. on January 11, 1984, without continuously monitoring gaseous gross and particulate activity. Proper flow was not maintained to the process vent radiation monitors RI-GW-101 and 102 due to a failure of the air sampling pump. The redundant process vent effluent radiation monitor RI-GW-130-1 was also inoperable due to equipment failures.

This is a Severity Level IV Violation (Supplement I), and applies to Unit 1.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: FEB 27 1984

8405300531 840522
PDR ADOCK 05000280
Q PDR