

# CP&L

Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT  
Post Office Box 790  
Hartsville, South Carolina 29550

APR 27 1984

MAY 3 12:43

Robinson File No: 13510E

Serial: RSEP/84-269

Mr. James P. O'Reilly  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
INSPECTION REPORT IER-83-024


Dear Mr. O'Reilly

Carolina Power and Light Company's November 3, 1984 response to the subject violation committed to revising procedures to functional test the safeguards test switch by March 31, 1984. The response also stated that, in the interim, work requests for testing these switches will contain a note to contact the I&C Foreman for post maintenance testing if the switch is replaced.

The interim action remains in effect. CP&L will schedule appropriate action on this item prior to startup. At present, a target date for procedure revision is August 3, 1984.

If you have any questions on this item, please contact me or my staff.

Very truly yours,



R. E. Morgan  
General Manager

H. B. Robinson S. E. Plant

CLW/pls

8405300539 840509  
PDR ADOCK 05000261  
Q PDR