

ENCLOSURE 1

NOTICE OF VIOLATION

Mississippi Power and Light Company
Grand Gulf

Docket No. 50-416
License No. NPF-13

The following violations were identified during an inspection conducted on February 16 - March 9, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

1. Technical Specification 6.8.1 requires written instructions be established, implemented, and maintained.

Contrary to the above, the requirements of Administrative Procedure 01-S-04-21, Revision 3, Emergency Preparedness Training Program were not met in that two response team members were assigned without having required current training.

This is a Severity Level IV violation (Supplement I).

2. 10 CFR 50, Appendix B, Criterion V, as implemented by the licensee's approved QA program MPL Topical-1A requires activities affecting quality be prescribed by documented instructions or procedures appropriate to the circumstances.

Contrary to the above, on March 7, 1984, procedures were not prescribed for appointing temporary mechanical maintenance supervisors.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: MAR 30 1984

8405300586 840514
PDR ADDOCK 05000416
G PDR