




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6631

May 22, 1984
RBG-17886
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-153

An interim or final status report concerning orifice plates supplied by Bailey Controls Company and manufactured by Allegheny Ludlum Steel Corporation and Eastern Stainless Steel Company will be provided by July 23, 1984.

Sincerely,

L. A. England for

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8406010101 840522
PDR ADDCK 05000458
S PDR

IE-27
10